

OFFICE MEMORANDUM

TO :

DATE:

C. A. Reynolds, Eng-4

10/11/63

Through :
FROM :

Dean Meyer, Group Leader, H-1

SUBJECT:

John Enders, H-2

SYMBOL :

Request for work order

Would you please write a work order to cover the following work?

1. Backfill to ground level, disposal wells # 70, 71, 72, 73, 74, 75
76, 77, 78, 79 and 82.
2. Move metal hole covers and place on disposal wells #80, 81 and 83.
3. Burn two buildings located in Pit #5, Area C (the Fire Dept. is supposed
to do this according to Homer Milford).
4. Cover material in Pit #5, Area C, that is located along the south
west side of the pit (including the remains to the two buildings in
item #3).
5. H-1 Group Section office at the CER Bld. will have to be notified
in advance of start of this work so as to provide Health Physics
support for this work.

John Enders

cc: File



8280