

PROPOSED EPA/EID HAZARDOUS WASTE INSPECTION SCHEDULE
JULY 14-15, 1986

July 14, 1987 - Tuesday

- 8:30 "IN BRIEFING" - DOE AREA OFFICE
- 9:30 REVIEW HAZARDOUS WASTE RELATED DOCUMENTS AT TA-50,
54 AND 59
BEGIN EPA CHECKLIST
TRAINING RECORDS
INSPECTION FORMS AND RECORDS
CLOSURE PLANS
PART B RELATED MATERIAL
EMERGENCY PLAN
WASTE ANALYSES RECORDS
- 12:00 LUNCH
- 1:00 CONTINUE COMPLETION OF EPA CHECKLIST
- TOUR MISC <90 DAY AND SATELLITE STORAGE AREAS
<90 DAY STORAGE AREAS
SM 40, 102 *Area*
TA-53-2
TA-46-88
TA-50-1 (BWTP AND IWTP)
TA 3-39 *Area*
SATELLITE STORAGE AREAS
SEE ATTACHED LIST

JULY 15, 1987 - WEDNESDAY

- 8:30 MEET AT TA-50
- 8:45 TOUR TA-50 BWTP AND INCINERATOR
- 10:30 TOUR TA-54 AREAS L AND G
- 12:00 LUNCH
- 1:00 TOUR BURN PITS/MAGAZINES - M AND WX DIVISIONS
INTERIM STATUS SITES
TA-16 BURN AREA AND AREA P
SCRAP HE DETONATION SITES
SATELLITE STORAGE FACILITIES
SEE ATTACHED LIST
<90 DAY STORAGE AREA
TA-22-40 (INACTIVE)
TA-40-2 (INACTIVE)
TA-16 BURN PADS
- 4:00 "OUT BRIEFING" - DOE AREA OFFICE OR TA-50



SATELLITE STORAGE AREAS

M DIVISION

1/2 scrap

TA 9-39, 21 (C)	TA 36-4, 5, 7, 11
TA 22-9-3, 34	TA 39-4
TA 14-22, 23	TA 40-6, 11, 14, 41, 23 (C)
TA 15-41, 242	TA 16-460 (C)

WX DIVISION

TA 16-260 HE CONTAMINATED OIL
-300 BARIUM NITRATE CONTAMINATED FLOOR SWEEPINGS
-302 HE CONTAMINATED RAGS/FLOOR SWEEPINGS
~~-304~~ WASTE ACETONE
~~-306~~ WASTE ETHANOL, ACETONE, CHLOROTHENE
~~-370~~ WASTE CHLOROTHENE (DEGREASER)
-430 SCRAP HE AND HE CONTAMINATED OIL
REST HOUSES (SERVICE MAGAZINES) - HE SCRAP
-221, 223, 225, 261, 263, 281, 283, 285, 303, 341,
343, 345, 360, 435, 437, 463

TA 11-36 SCRAP HE
-24 WASTE SOLVENTS

MEC DIVISION

Machine shops

TA 3-30	VACUUM PUMP REPAIR SHOP
TA 3-66	WASTE COOLANT/SOLVENT
TA 53-14	WASTE SOLVENTS
TA 33-39	WASTE OIL/SOLVENT
TA 39-2	WASTE SOLVENTS

PAN AM

~~TA 3-38~~ SOLVENTS
~~TA 3-70~~ KEROSENE
~~TA 3-382~~ SOLVENTS

MISC.

Chemical

TA 50-1	SOLVENTS/MISC. CHEMICALS
TA 3-66	MST-6
TA 43-1	SOLVENTS/MISC. CHEMICALS

SEE LIST OF CHEMICAL WASTE MANAGEMENT COORDINATORS - EACH COORDINATOR MAY HAVE ONE TO SEVERAL SATELLITE STORAGE FACILITIES UNDER HIS CONTROL.

Salvage yard

CHEMICAL WASTE MANAGEMENT COORDINATORS

Group	Contact	Area	Building	Phone Number	MS
M-DO	Frank Jackson	TA-8	21	7-5653	P915
M-1	Max Vigil	TA-9	29	7-4323	C920
M-1	Cal Maxwell	TA-9-14		7-4323	C920
M-4	Mike Christian	TA-15	40	7-4389	P940
M-6	Austin Bonner	TA-39	2	7-6592	J970
M-6	David Torres	TA-39	2	7-6383	J970
M-7	Billy Powell	TA-22	91	7-6770	J950
M-8	Selma Goldstein	TA-36	1	7-8051	J960
M-9	Ron Rabie	TA-40	1	7-4477	P952
MP-DO	Milt Hollen	TA-53	1	7-6176	H830
MP-DO	Don Cochran	TA-53	1	7-5763	H830
CLS-DO	Brad Martin	TA-46		7-6250	J563
CLS-1	Adele Hopkins	TA-3 (CMR)	29	7-4989	G740
CLS-1	Joel Dahlby	TA-3	29	7-9639	G740
CLS-2	Joel Dahlby	TA-3	29	7-9639	G740
CLS-5	Harvey Nutter	TA-35	2	7-4958	E535
CLS-7	Jerry Umphres (Oil only)	TA-35	245	7-2383	E525
Q-DO	Bill Wood	TA-46, 52, 35		7-3054 104-2245	E547
Q-2	Jake Martinez	TA-18		7-4617	J562
IS-DOT	Gerry Weber	TA- 3	28	7-7409	D417
IS-9	Jerry B. Halladay	3	43	7-5123	P350

CHEMICAL WASTE MANAGEMENT COORDINATORS

Group	Contact	Area	Building	Phone Number	MS
IS-10	Ken Johnson	3	SM-43,28	7-3152	P351
IS-12	Ann Marie Gorman	3	1559	7-4603	d416
MAT-1	Dan Doehling	3	170 (Gas Plant)	7-4406	P274
P-1	Browdie Anderson	TA-35	67	7-7600	E526
P-15	Fred W. Martinez	TA-3	216 422	7-5473 104-2185	D406
P-DO	Charles K. King	TA-35	87	7-5323 104-2190	E539
ESS-DO	Ken Joy	TA-33	Fenton Hill	7-9008	D446
INC-4	John Fitzpatrick	TA-46	88	7-4761	J568
INC-7	Gordan Knobloch	TA-41	1	7-4861	J514
INC-11	Calvin Longmire	TA-48	1	7-4948 7-4487	J514
E-5	Jack Chase	TA-3	SM-30 SM-40, DP	7-7497	D432
IT-DO	David Heimbach	TA-3	43	7-6922	B231
IT-6	Clifton R. Holman	TA-8	70	7-1316	P917
IT-7	Richard Robiinson	TA-3	43	7-6922	B231
HSE-1	Don Green			7-8296	K483
HSE-7	Charles Villareal	TA-50	WM-69	7-5397	E516
HSE-9	Diane Horn	TA-59	1 (OH-1)	7-6275	K484
MEC-DO	Rhonda Carpenter	TA-3	SM39	7-4651 104-2668	D472

CHEMICAL WASTE MANAGEMENT COORDINATORS

Group	Contacts	Area	Building	Phone Number	MS
J-6	Dale Engstrum	TA-16	S-Site	7-4246	C925
WX-DO	William Bradley			7-4307	P946
MST-3	George Melton	TA-21	DPE	7-9816	C348
MST-5	Bill Gibson	TA- 3	SM-29	7-2700	G730
MST-6	Joe Mitchell	TA-3	Sigma	104-2621 7-5479	G770
MST-7	Linda Wood	TA-35	213	7-0458	E549
MST-7	Jan Clements	TA-3	Sigma	7-5267	G770
MST-12	Jim Foxx	TA-55		7-2328	E501
MST-14	Jay Cook	TA-3	SM-29	7-4653	G742
MST-DO	Jim Bustamante (S. J.)	TA-3	SM-29	7-4563	G756
C-1	Joe Kleczka	TA-3	132	7-4584	B252
MEE-11	Ruth Sherman	TA-3	SM40	7-1805	D429
LANSC	Gail Legate	TA-53	MPF-7	7-3191	H805
PAN AM	Tom Holm-Hansen	TA-3		7-0104	A199
INC-4	Scott Kindead	TA-21		7-6045	C346
MST-5	Ron Livak	TA-35		7-1998	