



SUSANA MARTINEZ  
Governor  
JOHN A. SANCHEZ  
Lieutenant Governor

*mwl*  ENTERED  
NEW MEXICO  
ENVIRONMENT DEPARTMENT



2905 Rodeo Park Drive East, Building 1  
Santa Fe, New Mexico 87505-6303  
Phone (505) 476-6000 Fax (505) 476-6030  
[www.nmenv.state.nm.us](http://www.nmenv.state.nm.us)

RYAN FLYNN  
Cabinet Secretary  
BUTCH TONGATE  
Deputy Secretary

**CERTIFIED MAIL – RETURN RECEIPT REQUESTED**

March 10, 2015

Geoffrey L. Beausoleil  
Manager  
U.S. Department of Energy  
P.O. Box 5400, MS-0184  
Albuquerque, NM 87185-5400

Peter B. Davies  
Director,  
Nuclear Energy & Fuel Cycle Programs  
P.O. Box 6200, MS-0721  
Albuquerque, NM 87185

**RE: APPROVAL:  
MIXED WASTE LANDFILL GROUNDWATER MONITORING REPORT,  
MONITORING WELL MWL-MW4 METALS DATA, SEPTEMBER 2014  
PUMPING AND SAMPLING, JANUARY 2015  
SANDIA NATIONAL LABORATORIES, EPA ID# NM5890110518  
HWB-SNL-15-004**

Dear Mr. Beausoleil and Mr. Davies:


The New Mexico Environment Department (NMED) has reviewed the report *Mixed Waste Landfill Groundwater Monitoring Report, Monitoring Well MWL-MW4 Metals Data, September 2014 Pumping and Sampling*, dated January 2015, with cover letter dated February 18, 2015. NMED hereby approves the subject report.

The elevated metals observed in groundwater samples from well MWL-MW4 in 2013 were a result of corrosion of stainless steel well components, in particular the dedicated sampling pump. Steps taken to return the well and groundwater to normal conditions appear to be adequate.

If you have any questions regarding this letter, please contact Mr. William Moats of my staff at (505) 222-9551.

Mr. Beausoleil and Mr. Davies  
March 10, 2015  
Page 2

Sincerely,

  
John E. Kieling  
Chief  
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB  
W. Moats, NMED HWB  
L. King, EPA Region 6 (6PD-N)  
J. Cochran, SNL/NM, MS-0719  
J. Weckerle, SFO/ENG MS-0184

File: SNL 2015 and Reading