



BRUCE KING
GOVERNOR

State of New Mexico
ENVIRONMENT DEPARTMENT
Harold Runnels Building
1190 St. Francis Drive, P.O. Box 26110
Santa Fe, New Mexico 87502
(505) 827-2850

95AR3

JUDITH M. ESPINOSA
SECRETARY

RON CURRY
DEPUTY SECRETARY

#3

**CERTIFIED MAIL
RETURN RECEIPT REQUESTED**

January 25, 1995

Mr. David Neleigh, Chief
New Mexico Federal Facilities Section
EPA Region 6H-PN
Hazardous Waste Management Division
1445 Ross Avenue, Suite 1200
Dallas, Texas 75202

RE: Gandy-Marley Triassic Park Hazardous Waste Disposal Facility

Dear Mr. Neleigh:

Enclosed are copies of the RCRA (Parts A and B) permit Application and Appendices to the Application. The proposed disposal unit is located between the cities of Roswell and Tatum in southeastern New Mexico. The unit is 36 miles east of the city of Roswell and 42 miles west of Tatum as shown on the location map, Part B Permit Application, page 8 (highlighted).

The Hazardous and Radioactive Materials Bureau (HRMB) of the New Mexico Environment Department plans to conduct a RCRA facility Assessment (RFA) of the proposed "Triassic Park" landfill between February and March, 1995. This will be an attempt to identify, if any, Solid Waste Management Units or Areas of Concern at and around Triassic Park. The RFA will comprise three parts which include Preliminary Review, Visual Site Inspection, and Sampling, if appropriate. The findings from the RFA will be used to compile a report, a copy of which will be sent to you at the end of the RFA study.

If you have any questions you may call me or Cornelius Amindyas at (505) 827-4308. Thanks for your usual cooperation in our permitting process.

Sincerely,

Handwritten signature of Barbara Hoditschek in cursive.

Barbara Hoditschek, Manager
RCRA Permits Program
Hazardous and Radioactive Materials Bureau.

Enclosures (2)

cc: Benito Garcia, HRMB
File Red 95