



**TerraMatrix**

March 5, 1996

Mr. Bob Sweeny  
New Mexico Environment Department  
Hazardous and Radioactive Material Bureau  
2033 Galisteo St.  
Santa Fe, NM 87505



#10

Re: Gandy Marley Inc. Triassic Park Facility Liner Alternative HELP Analyses Figures 1, 2, and 3.

Dear Mr. Sweeny:

We are enclosing undated Figures 1, 2, and 3 to the Triassic Park Landfill Liner Alternative HELP Analyses (Revision 1) which you received Monday, March 4, 1996. Please insert these figures in the tabbed Figures Section of your report. These new figures illustrate the Gandy Marley proposed liner alternative (formerly Alternative 2), the revised cover section which includes the GCL replacement for 3 feet of clay and the MTR liner section. These figures are consistent with the cover demonstration presented in Revision 1 of the report.

If you have any questions or need additional information, please call me at (303) 763-5140.

Sincerely,

TerraMatrix Inc.

John J. Kendall  
Senior Engineer

Enclosures (3)

Engineering & Environmental Services  
165 South Union Boulevard, Suite 400  
Lakewood, Colorado 80228  
Phone 303.763.5140 Fax 303.763.8003