




Department of Energy
Carlsbad Field Office
P. O. Box 3090
Carlsbad, New Mexico 88221



JUL 11 2003

Mr. Carl E. Edlund, Director
Multimedia Planning and Permitting Division
6PD
USEPA Region 6
1445 Ross Avenue
Suite 1200
Dallas, TX 75202-2733

Subject: Submittal of Emergency Coordinator Names and Qualifications

Dear Mr. Edlund:

The purpose of this letter is to submit the list of names and qualifications of Resource Conservation Recovery Act (RCRA) Emergency Coordinators at the Waste Isolation Pilot Plant. This submittal is required by Condition of Approval VI.M.1 in the "Conditions of Approval for Disposal of PCB/TRU and PCB/TRU Mixed Waste at the U.S. Department of Energy (DOE) Waste Isolation Pilot Plant (WIPP) Carlsbad, New Mexico," May 15, 2003.

Enclosed is Attachment F (RCRA Contingency Plan), Table F-2 from the WIPP Hazardous Waste Facility Permit (HWFP). This table identifies the current list of names for each of the qualified RCRA emergency coordinators. The HWFP, Attachment F-2 requires a RCRA emergency coordinator to be on-site 24-hours per day.

The Facility Shift Managers serve as the primary RCRA emergency coordinator and the Facility Shift Engineers serve as the alternate. The enclosed page shows the minimum qualifications and training for the Facility Shift Managers and the Facility Shift Engineers. The Facility Shift Managers and the Facility Shift Engineers are trained in General Employee Training and Hazardous Waste Worker Training to identify and coordinate response to emergencies involving PCB containing wastes.

Sincerely,

Dr. Inés R. Triay,
Manager

Enclosure



Mr. Carl Edlund

-2-

cc: w/enclosure
N. Stone, EPA Region 6
C. Walker, Trinity Engineering
L. Roberts, EPA Region 6
J. Sales, EPA Region 6

cc: w/o enclosure
S. Martin, NMED
J. Kieling, NMED

