

Allen, Pam, NMENV

From: Maestas, Ricardo, NMENV
Sent: Wednesday, August 13, 2014 9:35 AM
To: Allen, Pam, NMENV
Subject: FW: WIPP Information - For Call Today
Attachments: 856 Filter Bank Plot_4-14.pdf; 857 Filter Bank Plot_4-14.pdf; WHT Plot_4-14.pdf

April

From: Kliphuis, Trais, NMENV
Sent: Wednesday, April 09, 2014 2:06 PM
To: Maestas, Ricardo, NMENV; Holmes, Steve, NMENV; Ines Triay (triyin@fiu.edu)
Subject: FW: WIPP Information - For Call Today

Trais Kliphuis
WIPP Staff Manager
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive E, Building 1
Santa Fe, New Mexico 87505

Office: 505-476-6051
Front Desk: 505-476-6000

From: Philip Theisen - ORISE [<mailto:Philip.Theisen@cbfo.doe.gov>]
Sent: Wednesday, April 09, 2014 1:34 PM
To: Oba Vincent; Kliphuis, Trais, NMENV; 'peake.tom@epa.gov'; 'Edwards, Jonathan'; 'Walsh, Jonathan'; 'Perrin, Alan'; 'Bob.Kehrman@wipp.ws'; 'Rick.Chavez@wipp.ws'; 'Stone.Nick@epa.gov'; Smith, Coleman, NMENV; 'brozowski.george@epa.gov'; 'Fraass, Ron'; 'Russell Hardy'; 'Veal.Lee@epamail.epa.gov'; 'Economy, Kathleen (Economy.Kathleen@epa.gov)'; 'Poppell, Sam W. (Poppell.Sam@epa.gov)'
Cc: George Basabilvazo - WIPPNet; 'Reynolds, Tammy - NWP (Tammy.Reynolds@wipp.ws)'; 'Pace, Berry (Berry.Pace@wipp.ws)'; 'Alton.Harris@em.doe.gov'; Susan McCauslin; 'Joe Harvill (jharvill@portageinc.com)'; 'Kennedy, Scott - NWP (Scott.Kennedy@wipp.ws)'; 'Jones, Stewart - RES'; 'Berta Oates'; 'schultheisz.daniel@epa.gov'; 'Dale Bignell'; Russ Patterson - WIPPNet; 'Kouba, Steve - WRES (Steve.Kouba@wipp.ws)'; Roger Nelson - WIPPNet
Subject: RE: WIPP Information - For Call Today

Attached are the excel plots for the filters.

Thank you,

Phil Theisen
ORISE Fellow
CBFO-DOE
575-234-7194 (Work)
734-735-1529 (Cell)

From: Oba Vincent
Sent: Wednesday, April 09, 2014 10:25 AM



To: 'Kliphuis, Trais'; 'peake.tom@epa.gov'; 'Edwards, Jonathan'; 'Walsh, Jonathan'; 'Perrin, Alan'; 'Bob.Kehrman@wipp.ws'; 'Rick.Chavez@wipp.ws'; 'Stone.Nick@epa.gov'; 'coleman.smith@state.nm.us'; 'brozowski.george@epa.gov'; 'Fraass, Ron'; 'Russell Hardy'; 'Veal.Lee@epamail.epa.gov'; 'Economy, Kathleen (Economy.Kathleen@epa.gov)'; 'Poppell, Sam W. (Poppell.Sam@epa.gov)'

Cc: George Basabilvazo - WIPPNet; 'Reynolds, Tammy - NWP (Tammy.Reynolds@wipp.ws)'; 'Pace, Berry (Berry.Pace@wipp.ws)'; 'Alton.Harris@em.doe.gov'; Susan McCauslin; 'Joe Harvill (jharvill@portageinc.com)'; 'Kennedy, Scott - NWP (Scott.Kennedy@wipp.ws)'; 'Jones, Stewart - RES'; 'Berta Oates'; 'schultheisz.daniel@epa.gov'; Philip Theisen - ORISE; 'Dale Bignell'; Russ Patterson - WIPPNet; 'Kouba, Steve - WRES (Steve.Kouba@wipp.ws)'; Roger Nelson - WIPPNet

Subject: WIPP Information - For Call Today

Attached is the action item listing, station A/B data, environmental samples tables, and the bioassay table.

Below is a summary of the discussion points for today: (Please note, activities and dates are subject to change. Please verify the most current dates of any information provided).

- Cleaning the soot from the fire out of the waste hoist tower is beginning today with the floors.
 - Water sample results from the rain event on 3/16 were received. All were less than MDC.
 - Dr. Albert Wiley, Director REAC/TS is on-site today and tomorrow conducting an independent review of the bioassay program and reviewing completed dose calculations. There are 12 urine samples and 3 fecal samples currently in the lab. The last WBC is scheduled for 4/22. The only remaining dose calculation (pending any more positive results) is related to the one positive urine sample. There are two samples yet to be submitted and 58 letters remaining to be issued. The target for completing all letters to the 149 personnel is 4/30.
 - Station A and B Sampling: The CAM at Station B is functioning. The safety basis strategy for the CAM utilization is being modified and will be resubmitted to DOE 4/9. Discussions are continuing regarding the CAM set point. The system is expected to go into service on 4/18. NWP hopes to return approximately 90 additional workers to the site on 4/21. (No change)
 - SS and AIS Shaft/Rope Inspections: The weekly MSHA compliance inspection for the AIS did not occur yesterday and is planned for today. The inspection of the SS will be done late today or tomorrow.
 - Contamination survey to the waste face (Phase 3): This is being broken into multiple activities:
 - *Activity 1:* Survey and proceed to airlock between W30 & E140 and to E140/S2000, scheduled for 4/12 or early next week
 - *Activity 2:* Survey and proceed to E140/S2520 to evaluate future safe operating base at the Waste Handling Lunchroom
 - *Activity 3:* Establish safe operating base in WH lunchroom and survey to W170/S2750
- Note: Activities 2 and 3 may be performed during the same entry, depending on contamination conditions
- *Activity 4:* Identify source at Panel 7 Waste Face
Or Identify source at Panel 6
- The filter change mock-up is planned for the week of April 14th. NWP has completed a critical review the filter replacement schedule and determined that they can be task ready on 5/12 (ten days earlier). The critical path, which is to provide makeup air for the fan. 34 (2 failed testing) HEPA filters are expected to arrive on 4/9. An additional 60 filters are expected on 4/17.
- Shipments of TRU waste from LANL to WCS are continuing. EPA is visiting WCS today.

A discussion will be held regarding the graphs that were sent out yesterday at the end of the meeting. The color code is as follows:

- Cyan = 1 Pre-Filter MOD


- Green = 2 Pre-Filter HIGH
- Yellow = 1st HEPA Bank
- Red = 2nd HEPA Bank

As a reminder, the call-in number is (866) 723-6758, code 8040901#


Thanks

Oba

41-B-856 Filter



41-B-857 Filter



Waste Hoist Tower

