


Monzeglio, Hope, NMENV

From: Steve Morris [smorris@giant.com]
Sent: Thursday, March 22, 2007 8:54 AM
To: Monzeglio, Hope, NMENV
Cc: Jim Lieb; Ed Riege
Subject: 2005 BW Samples - Metals
Attachments: HALL6322_000.pdf

Hope,

I've attached the analytical for the boundary wells from 2005.

As you can see, metals were not run on that series of wells.

We didn't notice my mistake until well into 2006.

In 2006 we hired a temporary helper for the Groundwater Sampling, and I expect to do the same this year.

The temp we use for this has several years experience doing groundwater sampling here at Ciniza.

This should help eliminate the chances of similar mistakes in the future.

Thanks,

Steve Morris

This inbound email has been scanned by the MessageLabs Email Security System.

Attached analytical in 2005 Annual GW Mon.rpt

Monzeglio, Hope, NMENV

From: Monzeglio, Hope, NMENV
Sent: Wednesday, March 21, 2007 2:36 PM
To: 'Jim Lieb'
Cc: Chavez, Carl J, EMNRD
Subject: Question on the GW Monitoring report

Jim

In the 2005 Ground Water Monitoring Report (Revised) it looks like metals were not analyzed for in the boundary well samples (e.g.,BW-1A). Was this an over sight and the data did not make it into the report or were metals not analyzed for? Metals is a requirement as specified in the table found in Section 2 (Scope of Activities) for the boundary wells.

Thanks

Hope

Hope Monzeglio
Environmental Specialist
New Mexico Environment Department
Hazardous Waste Bureau
2905 Rodeo Park Drive East, BLDG 1
Santa Fe NM 87505
Phone: (505) 476-6045
Main No.: (505-476-6000
Fax: (505)-476-6030
hope.monzeglio@state.nm.us

Websites:
New Mexico Environment Department
Hazardous Waste Bureau

Please note the new phone numbers