

WRG 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: WESTERN REFINING	Contact: Ed Riege
Address: I-40 / EXIT 39, JAMESTOWN, NM 87347	Telephone No. (505) 722-0258
Facility Name: WESTERN REFINING (GALLUP REFINERY)	Facility Type: Petroleum Refinery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Fect from the	North/South Line	Feet from the	East/West Line	County
	28	15 N	15 W					MCKINLEY

Latitude 35° 029' 024" Longitude 108° 024' 024"

NATURE OF RELEASE


Type of Release: Sulfur Dioxide (SO2) (Air Release)	Volume of Release 1738 pounds	Volume Recovered: N/A
Source of Release: Refinery Wide Power Outage	Date and Hour of Occurrence 07/04/15 @ 1337 hrs	Date and Hour of Discovery 07/06/15 @ 0800 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NRC (Kevin Williams- Rpt # 1121945); LEPC (Courtney); SERC (Yvone Gaintz); OCD (B. Powel/ C. Chavez); NMED (K. Vanhorn)	
By Whom? Ed Riege/Loretta Morgan	Date and Hour: 4/6/15-(07:49); (09:05); (0906); (1000, 1005); (10:10)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* No

Describe Cause of Problem and Remedial Action Taken.*
Western Refining (Gallup Refinery) experienced a power outage on July 4, 2015 due to Tri-state Power Company equipment issues from a rainstorm resulting in a facility wide power failure. The power failure lasted for about 2 hours, but access to continuous emission monitoring data and reports of monitoring conditions was not until Monday morning.

Describe Area Affected and Cleanup Action Taken.*
Tri-state was immediately notified of the issue and to obtain the necessary instructions for resetting the equipment so as to get the refinery online. 1738 pounds of Sulfur Dioxide (SO2) was released to the atmosphere over a two day period due to shutdown and startup of refinery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Riege	Approved by Environmental Specialist:	
Title: Environmental Manager	Approval Date:	Expiration Date:
E-mail Address: ed.riege@wnr.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/9/2015	Phone: (505) 722-0217	

* Attach Additional Sheets If Necessary