



DEPARTMENT OF THE AIR FORCE

HEADQUARTERS 27th FIGHTER WING (ACC)
CANNON AIR FORCE BASE, NEW MEXICO

*Steve Z
March 24
Hoditschek*

MAR 1994
RECEIVED
WASTE

04 MAR 1994

27 FW/CC
100 S DL Ingram Blvd Ste 100
Cannon AFB NM 88103-5214

Ms. Barbara Hoditschek
Program Manager, RCRA Permitting
New Mexico Environment Department
1190 St. Francis Drive
Santa Fe NM 87502

Dear Ms. Hoditschek

This letter is to inform you that visual inspections on Landfill 5 Cell 3 have revealed minor erosion on the soil cap. Work requests were processed to fill in the small ruts caused by storm water runoff. The work to fill in the ruts was completed on 10 Feb 94, by our civil engineer work force. At this time we plan to reseed the soil cap with a wild grass cover during the spring planting season.

These actions are necessary to protect the integrity of the soil cap over the landfill cell. Routine inspections on the soil cap will continue to ensure compliance with construction standards until a post closure permit is issued from your office.

The point of contact for this issue is Mr. John F. Ekhoﬀ at (505) 784-4639.

Sincerely

WILLIAM M. GUTH
Brigadier General, USAF
Commander