





DEPARTMENT OF THE AIR FORCE

HEADQUARTERS 27th FIGHTER WING (ACC) CANNON AIR FORCE BASE, NEW MEXICO

12 MAR 1997

Colonel W. P. Ard Commander, 27th Support Group 110 E Sextant Avenue Suite 1098 Cannon AFB NM 88130-5323



Mr. Benito J. Garcia, Chief Hazardous and Radioactive Materials Bureau New Mexico Environment Department 2044 Galisteo Street P O Box 26110 Santa Fe NM 87502



Dear Mr. Garcia

Attached are the sampling results for sampling performed at the downgradient wells at Landfill 5 on 16-17 Dec 96. We are gathering data by performing quarterly sampling at all wells at Landfill 5 for a period of one year. We will then have a statistical study done to determine background levels and determine if the landfill has had any effect on water quality.

If you have any questions, please contact Mr. Sanford Hutsell at (505) 784-6378.

Sincerely

W. P. ARD, Colonel, USAF Commander, 27th Support Group

Attachment:

Sampling Results at Landfill 5

cc:

NMED (C. Will) NMED w/o atch (S. Pullen) NMED GW Bureau (J. Jacobs) EPA Region VI (D. Neleigh) HQ ACC CES/ESVW w/o atch (M. Calvert)



Cannon Air Force Base, New Mexico RCRA Ground-Water Sampling at Landfill 5 Data Report for December 16-17, 1996 Sampling

Prepared for

United States Air Force Air Combat Command Cannon Air Force Base, New Mexico 88103

February 27, 1997

Prepared by

U.S. Geological Survey, Water Resources Division 4501 Indian School Road NE Suite 200 Albuquerque, New Mexico 87110