



CAFBOO
DEPARTMENT OF THE AIR FORCE
27th CIVIL ENGINEER SQUADRON (ACC)
CANNON AIR FORCE BASE NEW MEXICO

~~CAFBOO-00-009~~

Glen

Lt Col Eric J. Wilbur
Commander
506 N DL Ingram Blvd
Cannon AFB NM 88103-5003



10 JUL 2000

Mr. James Bearzi, Chief
Hazardous and Radioactive Materials Bureau
New Mexico Environment Department
2044 Galisteo Street
P.O. Box 26110
Santa Fe NM 87502

Dear Mr. Bearzi

Attached for your information and record is the 1999 *Annual Evaluation of Bioventing Soil Remediation at SWMU 70, Oil/Water Separator No. 326, Cannon Air Force Base, New Mexico.*

The remediation activity is in the sixth year of operation and continues to illustrate reduction in the soil contamination. Cannon Air Base is proposing continuation of the remedial operation through 2001 and anticipates acceptable cleanup levels will be achieved towards the end of the year.

If you have any questions or concerns regarding restoration activities at Cannon Air Force Base, please contact Mr. Sanford D. Hutsell, or Mr. John S. Pike at (505) 784-6022.

ERIC J. WILBUR, Lt Col, USAF

Attachment:
**Annual Evaluation of Bioventing
Soil Remediation at SWMU 70,
Oil/Water Separator No. 326**

cc:
NMED w/o atch (G. VonGonten)
NMED (J. Jacobs)
EPA Region VI (B. Sturdivant)

Document
Not Found