

HWB PHOTO SHEET



Facility: Central Paint & Body Shop


Photo #: 1

Date/Time: 7-23-09/11:40 a.m.

Location: Southside of building next to fence..

Description: Two 55-gallon drums. Only one had hazardous waste. Labeled and closed.

Violation(s): NA



Facility: Central Paint & Body Shop

Photo #2

Date/Time: 7-23-09 /11:35 a.m.

Location: Mixing room.

Description: One small container with product that is used to make paint. Non-hazardous.

Violation(s): NA