

# HWB PHOTO SHEET



**Facility:** AAMCO Transmissions


**Photo #:** Aerial

**Date/Time:** 5/2/22 10:00am

**Location:** 6629 Lomas Ave.

**Description:** Overview of the facility.

**Violation(s):** None.



**Facility:** AAMCO Transmissions

**Photo #:** Street View

**Date/Time:** 5/2/22 10:00am

**Location:** 6629 Lomas Ave.

**Description:** Street view of the facility.

**Violation(s):** None.



HWB PHOTO SHEET

**Facility:** AAMCO  
Transmissions


**Photo #:** AAMCO 1

**Date/Time:** 5/2/22 11:22am

**Location:** Garage located in the northeast corner of the property.

**Description:** Transmissions are assembled and broken down on the table which collects the transmission fluid and pipes the fluid to a storage tank outside.

**Violation(s):** None.



**Facility:** AAMCO  
Transmissions


**Photo #:** AAMCO 2

**Date/Time:** 5/2/22 11:22am


**Location:** Garage located in the northeast corner of the property.

**Description:** Used oil from around the shop is staged in the drum and piped into the storage tank outside.

**Violation(s):** None.



HWB PHOTO SHEET



**Facility:** AAMCO  
Transmissions

**Photo #:** AAMCO 6

**Date/Time:** 5/2/22 11:26am

**Location:** North side of the building.

**Description:** Used oil tank  
oil from the garage is piped  
to the tank for storage.

**Violation(s):** None.

**Facility:**

**Photo #:**

**Date/Time:**

**Location:**

**Description:**

**Violation(s):**