

HWB PHOTO SHEET



**Facility:** ABCWUA Plant

**Photo #:** 2326

**Date/Time:** 1/25/11 4:19pm

**Location:** South side of  
Cogeneration Bldg.

**Description:** Left hand valve  
is for the Used Oil tank in  
the floor of the building.

**Violation(s):** None.



**Facility:** ABCWUA Plant

**Photo #:** 2335

**Date/Time:** 1/26/11  
10:44am

**Location:** Vehicle  
Maintenance Shop

**Description:** Used Oil tank  
with a used oil filter drain on  
top of lid.

**Violation(s):** None.

HWB PHOTO SHEET



**Facility:** ABCWUA Plant

**Photo #:** 2346

**Date/Time:** 1/26/11  
11:25am

**Location:** East side of Water Lab.

**Description:** Trailer is used to store hazardous waste and is taken off every two months to Rinchem.

**Violation(s):** None.

**Facility:**

**Photo #:**

**Date/Time:**

**Location:**

**Description:**

**Violation(s):**