



NEW MEXICO ENVIRONMENT DEPARTMENT



Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303
Phone (505) 476-6000 Fax (505) 476-6030
www.nmenv.state.nm.us

HAZARDOUS WASTE COMPLIANCE EVALUATION REPORT

Evaluation Type: CEI [X] CAV \_\_\_ Other \_\_\_

Facility: ABC Machine Shop Location: 1005 GRIMES ST
EPA ID #: NMD 986682144 Location: HOBBS NM 88240
Ownership: Prentis Sturdivant Mailing Address: PO Box 2401
HOBBS NM 88241
Facility Representative/Contact: [Signature] Title: OWNER
Date: 11-6-2013 Time of Entry: 1:10

Entry Conference:

- Present credentials to facility representative [check]
Cite authority to enter site, conduct inspection, obtain samples, take photos (NMSA § 74-4-4.3) [check]
State reasons(s) for and nature of inspection [check]
State objectives and procedures for inspection [check]

Participants: Print:

Table with 3 columns: Name, Title, Phone#. Rows include Michael Duran (EQU Specialist, 505-660-1886), Don Meyer (Environmental Specialist, 505-222-9554), and Prentis B. Sturdivant (owner, 575-369-5836).

**Compliance Evaluation Inspection, Better Business Practices**

Facility ABC Machine Shop EPA # NMD986682144 DATE 11/6/13

| Pollution Prevention & Waste Minimization Suggestions |
|---|
|   |
|   |
|   |
|   |
|   |
|   |
|   |
|   |
|   |
|   |
|   |

| Questions, Concerns, Comments                      |
|--|
| Shop is very clean & use of diesel is a good idea. |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

Facility ABC Machine Shop

EPA # NMD986682144

Date 11/6/13

Process Information

| Waste Type & Code               | Process, Location/How Managed<br>Transporter & Destination   | Est. Quantity per month |
|---------------------------------|--|-------------------------|
| Sand blasting<br>non hazardous  | use Tungsten Carbide <del>rock</del> blast media which is recycled.  | < 1 lb.                 |
| Parts washing<br>Diesel non haz | use diesel in parts washer in place of solvent<br>Used up in process.  |                         |
| Used oil                        | Denbox oil from grain elevators staged in 55 gal drum for several years not filled & set in equipment yard on west side of shop. |                         |
| Aerosol cans                    | Used for touch up & some primer work<br>Cans are used up & punctured prior to placement in trash                                 | ≈ 30                    |

This Compliance Evaluation Inspection (CEI)  
was conducted based on:

EPA ID NMD986682144  
Facility Name ABC Machine Shop  
Date 11-6-2013

Reason for Inspection: Routine  Compliant  Follow-up   
Never Been Inspected

Facility was Last Inspected on: \_\_\_\_\_  
Facility is: Notifier  Non-Notifier

History, Size and Nature of Business: ABC Machine Shop has been in  
business since 1983. The facility consists of a 4800 sq. ft.  
shop on ~ 1/2 acre. The nature of the business is general  
machinery work. There are 2 full time and 1 part time  
employees. Hours of operation are 7-5 M-F.

Waste Processes Forms  
 Potential Violation(s) Forms  
Checklists Completed: CESQG  SQG  <90 Day  Used Oil  Other: \_\_\_\_\_

Current Status: CESQG  SQG  LQG  TSD  Compliant Response   
Transporter  Recycler  Non-Handler  Other: \_\_\_\_\_

Results of Inspection: Conducted an in brief with owner  
Pamela Sturdivant. Followed with a walk through of the  
shop area and surrounding yard. The facility is a  
Conditionally exempt Small Quantity Generator (CESQG).  
There were no areas of concern noted during  
inspection.

