

HWB PHOTO SHEET

Facility: Flying J Truck Plaza #689

Photo #: 0598

Date/Time: 1/05/18 1:29 pm

Location: Central accumulation area on the north side of the convenience center.

Description: Diesel related wastes one drum for liquids and one for solids.

Violation(s): None.

Facility: Flying J Truck Plaza #689

Photo #: 0599

Date/Time: 1/05/18 1:30 pm

Location: Central accumulation area.

Description: Grit is from cleaning the sump near the diesel dispensers.

Violation(s): None.



HWB PHOTO SHEET

Facility: Flying J Truck Plaza #689

Photo #: 0600

Date/Time: 1/05/18 1:30 pm

Location: Central accumulation area.

Description: Absorbent pads associated with the diesel dispensers.

Violation(s): None.

Facility: Flying J Truck Plaza #689

Photo #: 0609

Date/Time: 1/05/18 1:38 pm

Location: central accumulation area facing east.

Description: Wastes generated from the truck stop are staged here.

Violation(s): None.

