




REPLY TO  
ATTENTION OF:

  
**DEPARTMENT OF THE ARMY**  
US ARMY INSTALLATION MANAGEMENT COMMAND  
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS  
1 PERSHING ROAD  
FORT BLISS, TEXAS 79916-3803



December 17, 2009

Environmental Division

Mr. David Cobrain  
Project Leader  
New Mexico Environmental Department-HWB  
2905 Rodeo Park Drive East, Building 1  
Santa Fe, New Mexico 87505-6303


Dear Mr. Cobrian:

On October 15, 2009, the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site Inspection of the McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 29/FTBL-011 per NMED letter dated May 27, 2008. The correspondence indicated that the following information must be included in the site inspection; observations of the run-on controls, landfill cover and submit photographs and descriptions of the site to NMED annually. The cover and the native vegetative conditions of SWMU-29 landfill are in very good condition.

During the inspection of October 15, 2009, a hole was found, approximately in the center of the landfill. The excavated debris was placed back into the hole and covered with clean inert soil.

If you have any questions concerning this report, please do not hesitate to contact Ron Baca, at 915-568-7979, ron.baca@us.army.mil.

Sincerely,

  
for Keith Landreth  
Chief, Environmental Division  
Directorate of Public Works

Enclosures

## ENVIRONMENTAL PERFORMANCE ASSESSMENT

IMSW-BLS-DPW-E

01 December 2009

MEMORANDUM FOR (Program Manager), ATTN: Mr. Ron Baca

SUBJECT: DPW- Environment Division EPAS Inspection.

1. On 15 October 2009, the DPW- Environment Division Environmental Performance Assessment System (EPAS) team conducted the annual compliance audit of Fort Bliss Solid Waste Management Units (SWMU) 18, (SWMU) 27 and (SWMU) 29. The attached report lists findings of noncompliance, corrective actions, and regulatory references.
2. If you have questions/comments regarding this report, please contact Isaac Trejo, DPW-E Division, 569-6297, or myself at 568-3782.

*Sylvia Q. Waggoner*  
for KEITH LANDRETH, CHIEF  
DPW-Environmental Division

## ENVIRONMENTAL PERFORMANCE ASSESSMENT

Unit: IMSW-BLS-DPW-E

Assessment Date: 10-15-2009

Facility ID: FTBL-11

Facility Name: SWMU-29

P.O.C: Ron Baca

Telephone Number: 568-7979

Assessor: Isaac Trejo

Telephone Number: 569-6297

### LIST OF OBSERVATIONS:

**1. Finding:** A hole was found in the middle of the landfill.

**Citation:** 40 CFR 258.61(a) Verify that post closure and effectiveness of any final cover, including making repairs to the cover as necessary to correct the effects of settlement, subsidence, erosion, and to prevent run-on and run-off from eroding or otherwise damaging the final cover.

**Corrective Action:** Placed excavated debris back into hole and provide final cover with inert soil.

**2. Positive Observation:** Erosion was not found at this landfill.

**3. Positive Observation:** Vegetation is very healthy on the surrounding area of the landfill and on the final cover.

Finding 1.	Hole was found in the middle of the landfill
	

# ENVIRONMENTAL PERFORMANCE ASSESSMENT

	Debris was put back on hole and final cover applied.	
Corrected finding.		

Observations 1 & 2	Erosion was not found at this landfill and Vegetation is very healthy	
		