



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1 PERSHING ROAD
FORT BLISS, TEXAS 79916-3803

ENTERED



October 13, 2010

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On September 15, 2010, the Directorate of Public Works, Environmental Division, Performance Assessment System (EPAS) team conducted the annual Post-Closure Site Inspection of the Closed McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 18/FTBL-013 as per NMED letter dated June 12, 2007. The correspondence indicated that the following information must be included in the site inspection; observations of the cover i.e. cap, drainage system, and vegetation and submit photographs and descriptions of the site to NMED.

During the inspection of September 15, 2010, the cover of SWMU-18 was found to be in very good condition. Vegetation has continued to spread throughout the landfill cover and the vegetation in and around the drainage system is extremely robust. No EPAS findings were observed at the time of the inspection.

If you have any questions concerning this report please do not hesitate to contact Ron Baca, at (915) 568-7979, or email Mr. Baca at the following address ron.baca@us.army.mil.

Sincerely,

Vicki Hamilton
Chief, Environmental Division
Directorate of Public Works

Enclosures

ENVIRONMENTAL PERFORMANCE ASSESSMENT

IMSW-BLS-DPW-E

04 October 2010

MEMORANDUM FOR (Program Manager), ATTN: Mr. Ron Baca

SUBJECT: DPW- Environment Division EPAS Inspection.

1. On 15 September 2010, the DPW- Environment Division Environmental Performance Assessment System (EPAS) team conducted the annual compliance audit of Fort Bliss Solid Waste Management Units (SWMU) 18. The attached report lists observations made during this audit.

2. If you have questions/comments regarding this report, please contact Isaac Trejo, DPW-E Division, 568-8421, or myself at 568-7031.


SYLVIA WAGGONER
DPW-E Multimedia Chief

FOR OFFICIAL USE ONLY

ENVIRONMENTAL PERFORMANCE ASSESSMENT

LIST OF OBSERVATIONS:

Unit: IMSW-BLS-DPW-E

Assessment Date: 09-15-2010

Facility ID: FTBL-13

Facility Name: SWMU-18

P.O.C: Ron Baca

Telephone Number: 568-7979

Assessor: Isaac Trejo

Telephone Number: 569-6285

LIST OF OBSERVATIONS:


- 1. Positive observation:** No erosion was found at this landfill
- 2. Positive observation:** Vegetation was very healthy in the middle of the landfill and at the edges of the landfill.
- 3. Positive observation:** Fence surrounding landfill and entrance gate did not have any deficiencies.

Photo index

Positive observation #1	No erosion was found at this landfill
	

FOR OFFICIAL USE ONLY

ENVIRONMENTAL PERFORMANCE ASSESSMENT

Positive observation #2	Vegetation was very healthy in the middle of the landfill and at the edges of the landfill.
	

Positive observation #2	Fence surrounding landfill and entrance gate did not have any deficiencies.
	

FOR OFFICIAL USE ONLY