




**DEPARTMENT OF THE ARMY**  
US ARMY INSTALLATION MANAGEMENT COMMAND  
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS  
1 PERSHING ROAD  
FORT BLISS, TEXAS 79916-3803

REPLY TO  
ATTENTION OF:

December 21, 2010



Environmental Division

Mr. David Cobrain  
Project Leader  
New Mexico Environmental Department-HWB  
2905 Rodeo Park Drive East, Building 1  
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On December 7, 2010, the Directorate of Public Works, completed the first biennial inspection of the Inactive McGregor Range Open Detonation (IMROD) area, Solid Waste Management Unit (SWMU-20/FTBL-015 as per NMED letter dated October 7, 2009. The correspondence indicated that the following information must be included in the site inspection; a map depicting the area inspected and the location(s) of any MPPEH removed during the inspection/work. The permittee must implement institutional controls at the including posting warning and restrict the access to the land.

During the Inspection/work no MPPEH was encountered and both a fence and signage were installed to restrict access to the site.

If you have any questions concerning this report, please do not hesitate to contact Ron Baca, at 915-568-7979, [ron.baca@us.army.mil](mailto:ron.baca@us.army.mil) or Joel Reyes, at 915-568-6364, [joel.reyesjr@us.army.mil](mailto:joel.reyesjr@us.army.mil).

Sincerely,

*Rafael Comal, Ph.D.*

For:

Vicki G. Hamilton  
Chief, Environmental Division  
Directorate of Public Works

Enclosures