



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1 PERSHING ROAD
FORT BLISS, TEXAS 79916-3803



ENTERED



December 12, 2011

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On April 28, 2011, the Directorate of Public Works, Environmental Division Performance Assessment System (EPAS) team conducted the annual Post-Closure Site Inspection of the Closed McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 18/FTBL-013 as per NMED letter dated June 12, 2007. The correspondence indicated that the following information must be included in the site inspection; observations of the cover i.e. cap, drainage system, and vegetation and submit photographs and descriptions of the site to NMED.

During the inspection of April 28, 2011, the cover of SWMU-18 was found to be in very good condition. Vegetation has continued to spread throughout the landfill cover and the vegetation in and around the drainage system is extremely robust. No EPAS findings were observed at the time of the inspection.

If you have any questions concerning this report, please do not hesitate to contact Joel Reyes, at 915-568-6993, joel.reyes20.civ@mail.mil or Ron Baca, at 915-568-7979, ronald.h.baca.ctr@mail.mil.

Sincerely,

Vicki G. Hamilton, R.A.
Chief, Environmental Division
Directorate of Public Works

Enclosures

ENVIRONMENTAL PERFORMANCE ASSESSMENT

Unit: IMWE-BLS-PWE

Assessment Date: 04-28-2011

Facility ID: FTBL-13

Facility Name: SWMU-18

P.O.C: Ron Baca

Telephone Number: 568-7979

Assessor: Julio Castro

Telephone Number: 892-0335

List OF Observations:

1. Positive Observation: Erosion was not found at this landfill.
2. Positive Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.
3. Positive Observation: Gate and fences were in good condition.

<u>Observations</u> <u>1 & 2</u>	
	

<u>Observation #3</u>	
	

ENVIRONMENTAL PERFORMANCE ASSESSMENT

2. **Finding:** On the 4 October 2011, (Before)

A. The arroyo berm on the northeast portion of the landfill showed signs of erosion.



FOR OFFICIAL USE ONLY

ENVIRONMENTAL PERFORMANCE ASSESSMENT

3. **Corrective Action:** On the 4 November 2011 the follow action was taken, (After)

A. The erosional features on the arroyo berm on the northeast portion of the landfill were repair.



FOR OFFICIAL USE ONLY