



REPLY TO
ATTENTION OF:

DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1 PERSHING ROAD
FORT BLISS, TEXAS 79916-3803

 **ENTERED**



December 12, 2011

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303


Dear Mr. Cobrain:

On April 28 2011, the Directorate of Public Works, Environmental Division Performance Assessment System (EPAS) team conducted the annual Post-Closure Site inspection of the Dona Ana Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 29/FTBL-011 as per NMED letter dated May 27, 2008. The correspondence indicated that the following information must be included in the site inspection; observations of the run-on controls, landfill cover and submit photographs and descriptions of the site to NMED annually.

During the audit of April 28 2011, the cover and the native vegetative conditions of SWMU-29 landfill were found in very good condition. There were no EPAS findings during this inspection.

If you have any questions concerning this report, please do not hesitate to contact Joel Reyes, at 915-568-6993, joel.reyes20.civ@mail.mil or Ron Baca, at 915-568-7979, ronald.h.baca.ctr@mail.mil.

Sincerely,



Vicki G. Hamilton, R.A.
Chief, Environmental Division
Directorate of Public Works

Enclosures

ENVIRONMENTAL PERFORMANCE ASSESSMENT

Unit: IMWE-BLS-PWE

Assessment Date: 04-28-2011

Facility ID: FTBL-11

Facility Name: SWMU-29

P.O.C: Ron Baca

Telephone Number: 568-7979

Assessor: Julio Castro

Telephone Number: 892-0335

List OF Observations:

1. Positive Observation: Erosion was not found at this landfill.
2. Positive Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.
3. Positive Observation: Gate and fences were in good condition.

<u>Observations</u> <u>1 & 2</u>	
	

<u>Observation #3</u>	
	