



SUSANA MARTINEZ  
Governor  
JOHN A. SANCHEZ  
Lieutenant Governor

NEW MEXICO  
ENVIRONMENT DEPARTMENT

2905 Rodeo Park Drive East, Building 1,  
Santa Fe, NM 87505-6303  
Phone (505)476-6000 Fax (505) 476-6030  
www.nmenv.state.nm.us



RYAN FLYNN  
Cabinet Secretary  
BUTCH TONGATE  
Deputy Secretary

**CERTIFIED MAIL – RETURN RECEIPT REQUESTED**

July 1, 2014

Vicki G. Hamilton, R.A.  
Chief, Environmental Division  
Directorate of Public Works  
Department of the Army  
Headquarters, U.S. Army Garrison Command  
1741 Marshall Road  
Fort Bliss, TX 79916-3803

**RE: REVIEW  
ANNUAL POST-CLOSURE SITE INSPECTION REPORT  
FTBL-11/SWMU 29 ADJACENT AREAS RUN-ON CONTROL DOÑA ANA  
RANGE CAMP LANDFILL  
FORT BLISS, NEW MEXICO  
EPA ID #NM4213720101  
HWB-FB-14-002**

Dear Ms. Hamilton:

The New Mexico Environment Department (NMED) has reviewed the Department of Army's (Permittee) *Post-Closure Site Inspection of the Doña Ana Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 29/FTBL-011*, Fort Bliss, New Mexico (Report), dated January 2, 2014, and received January 8, 2014.

In accordance with NMED's *Approval of FTBL-11/SWMU-29 Adjacent Run-on Controls, Doña Ana Range Camp, Fort Bliss, New Mexico* (May 27, 2008), the Permittee conducted an inspection of the site on May 30, 2013, and found it to be in good condition. According to the information provided, minor erosion was observed on May 30, 2013, at the landfill site. The Permittee must continue to monitor this erosion and demonstrate that it is not adversely affecting the landfill cover. According to the report, healthy vegetation growth was observed on the final landfill cover, and the signage on the gates and fences was found to be in good condition.

Ms. Hamilton


July 1, 2014

Page 2

The Permittee has fulfilled its obligation to conduct the annual site inspection and submit an annual report to NMED. In the future, the Permittee must provide an approximation of distance between an erosion feature and the capped area, and continue to provide photographs and descriptions of site conditions and any repair work performed. Permittee must continue to conduct annual inspections at SWMU 29 and submit a report to NMED documenting results of the inspection. The inspection report for next year is due no later than December 31, 2014.

Please contact Siona Briley (505) 476-6049 if you have any questions regarding this letter.

Sincerely,



John E. Kieling  
Chief  
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB  
S. Briley, NMED HWB  
N. Dhawan, NMED HWB  
V. Hamilton, DoA, Ft. Bliss

File: Ft. Bliss (SWMU 29) Annual Site Inspection Report  
FB-14-002