



SUSANA MARTINEZ
Governor
JOHN A. SANCHEZ
Lieutenant Governor

NEW MEXICO
ENVIRONMENT DEPARTMENT

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303
Phone (505) 476-6000 Fax (505) 476-6030



RYAN FLYNN
Cabinet Secretary-Designate
BUTCH TONGATE
Deputy Secretary

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

August 7, 2015

Sylvia A. Waggoner
Chief, Compliance Branch
Department of the Army
Headquarters, U.S. Army Garrison Command
1733 Pleasonton Road
Fort Bliss, TX 79916-6816

RE: REVIEW
ANNUAL INSPECTION OF SOLID WASTE MANAGEMENT UNIT 27
(SWMU 27)/FTBL-012 DOÑA ANA RUBBLE LANDFILL
FORT BLISS, NEW MEXICO
EPA ID #NM4213720101
HWB-FB-14-008

Dear Ms. Waggoner:

The New Mexico Environment Department (NMED) has received Fort Bliss's *Annual Inspection of Solid Waste Management Unit 27 (SWMU 27)/FTBL-012 Doña Ana Rubble Landfill*, dated December 12, 2014, and received December 18, 2014.

In accordance with NMED's *Approval of Post Closure Certification Report for Doña Ana Range Camp Landfill (Solid Waste Management Unit No. 27)*, October 30, 2007, the Permittee conducted an inspection of the site on June 19, 2014. During the inspection no erosion was observed on the cap or on the perimeter of the landfill. According to the information provided, on June 19, 2014, healthy vegetation growth was observed on the final landfill cover and on the surrounding area. Gates and fences were found to be in good condition.

A second inspection was conducted after the rainy season on October 2, 2014. Damage or erosion was not observed. According to the information provided, healthy vegetation growth was observed on the final landfill cover and on the surrounding area. Gates and fences were found to be in good condition.


Ms. Waggoner
August 7, 2015
Page 2

The Permittee has fulfilled its obligation to conduct biannual site inspection and submit an annual report to NMED. The Permittee must continue to conduct biannual inspections at SWMU-27, after snowmelt and at the end of the rainy season (*i.e.*, the North American monsoon season which ranges from June-Mid September) so that any damage caused by rain or snowmelt can be evaluated and repaired, if needed. The Permittee must submit annual reports to NMED documenting the results of the inspections.

The inspection report for next year is due no later than December 31, 2015.

If you have any questions regarding this letter, please contact Siona Briley (505) 476-6049.

Sincerely,



John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
S. Briley, NMED HWB
V. Hamilton, DoA, Ft. Bliss

File: Ft. Bliss (SWMU 27) Annual Site Inspection Report
FB-12-003