



Michelle Lujan Grisham
Governor

Howie C. Morales
Lt. Governor

NEW MEXICO
ENVIRONMENT DEPARTMENT 

Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6313
Phone (505) 476-6000 Fax (505) 476-6030

www.env.nm.gov

CERTIFIED MAIL - RETURN RECEIPT REQUESTED



James C. Kenney
Cabinet Secretary

Jennifer J. Pruett
Deputy Secretary

MAY 06 2020

Jesus D. Moncada
Chief, Compliance Branch
US Army Fort Bliss Garrison
DPW-Environmental Division
Building 622, Taylor Road
Fort Bliss, TX 79916-3803

**RE: REVIEW
ANNUAL POST-CLOSURE SITE INSPECTION REPORT
MCGREGOR RANGE CAMP LANDFILL
FORT BLISS SITE NO. 13 (FTBL-013)/SOLID WASTE MANAGEMENT UNIT 18
(SWMU 18)
FORT BLISS, NEW MEXICO
EPA ID #NM4213720101
HWB-FB-20-001**

Dear Mr. Moncada:

The New Mexico Environment Department (NMED) has reviewed the Department of Army (Permittee) *Annual Post-Closure Site Inspection Report McGregor Range Camp Landfill, Fort Bliss Site No. 13 (FTBL-013)/Solid Waste Management Unit 18 (SWMU 18) Fort Bliss, New Mexico*, received January 8, 2020.


In accordance with NMED's *Approval of Post-Closure Certification Report for McGregor Range Camp Landfill (Solid Waste Management Unit No. 18), Fort Bliss, New Mexico*, dated June 12, 2007, the Permittee conducted an inspection of the site on December 12, 2019, and found the landfill cover, drainage structure, vegetative layer, perimeter fence and warning signs to be in good condition.

Mr. Moncada
Post-Closure Inspection Report – SWMU 18
Page 2

The Permittee has fulfilled its obligation to conduct the annual site inspection and submit an annual report to NMED. The Permittee must continue to conduct annual inspections at SWMU 18 and submit the associated report to NMED documenting results of the inspection. The inspection report for next year is due no later than **December 31, 2020**.

If you have any questions regarding this letter, please contact Michiya Suzuki (505) 476-6059.

Sincerely,



Kevin Pierard
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
M. Suzuki, NMED HWB
L. King, EPA Region 6 (6LCRRC)
R. Crites, Fort Bliss

File: 2020 Ft. Bliss (SWMU 18) Annual Site Inspection Report