




Apparatus Service  
General Electric Company  
1 West Broad Street, Albany, NY 12205

April 25, 1990

Boyd Hamilton  
State of New Mexico  
Environmental Improvement Division  
Harold Runnels Bldg.  
1190 St. Francis Drive  
Santa Fe, New Mexico 87503



SUBJECT: Monitoring Well Locations  
GE Apparatus Service Shop  
Albuquerque, New Mexico

Dear Mr. Hamilton:

Attached is a copy of a drawing marked with the approximate locations of the installed piezometers and the locations for the installation of the monitoring wells discussed with you and approved by Kathleen O'Reilly of USEPA Region 6.

Very truly yours,

Barry R. York  
Environmental Project Manager

cc: K.L.O'Reilly, USEPA, Region 6  
A.D. Alcott, Law Env.Inc.

