



Apparatus Service Department
General Electric Company
1 River Rd., Bldg. 6, 2nd Floor, Schenectady, NY 12345
Bldg. 6, Rm. 211
Tel. (518) 385 0545

June 11, 1990

Section Chief, Technical Section (6H-CX)
RCRA Enforcement Branch (6H-C)
United States Environmental
Protection Agency
1445 Ross Avenue
Dallas, Texas 75202-2733

Kathleen O'Reilly (6H-CX)
United States Environmental
Protection Agency
1445 Ross Avenue
Dallas, Texas 75202-2733

Boyd Hamilton
State of New Mexico
Environmental Improvement Division
Harold Runnels Bldg.
1190 St. Francis Drive
Santa Fe, New Mexico 87503

Subject: Monthly Progress Report 11
General Electric Consent Decree
Civil Action No. 87-1073-jb

Percentage of RFI Work Plan completed - 75%.

Ground water samples were obtained and sent for analysis for Appendix IX constituents.

Soil samples were obtained from the site on an approximate 40 foot grid and sent for analysis.

Soil samples were obtained from four borings made to depths of twenty feet and sent for analysis.

Borings were made in a total of nine locations in the vicinity of the dry well due to the field GC analyses showing constituents in one of the five planned peripheral borings. Analysis for halogenated volatile organics (Method 8010) will be added to the analyses performed on the samples obtained from the four additional borings.

Planned activities for the next reporting period include the following:

Complete laboratory analyses of ground water and soil samples.

Obtain air samples for the air emissions study.

Very truly yours,



Barry York
Environmental Project Manager

albuq11.wp

cc: Office of Regional Counsel, USEPA, 1445 Ross Ave., Dallas, Texas 75202-2733
AD Alcott, Law Environmental, Inc., 112 Townpark Drive, Kennesaw, GA., 30144-5599
PRC Environmental Management, Inc., American Financial Center, Bldg.4, Suite 225, 2400 Louisiana Blvd., NE, Albuquerque, NM 87110
JT Harrsen, GE, Albany
GR Logan, GE, Schdy.
WP Thornton, GE, Schdy.