



Bldg. 6, Rm. 211  
Tel. (518)-385-0545

September 11, 1990

Section Chief, Technical Section (6H-CX)  
RCRA Enforcement Branch (6H-C)  
United States Environmental  
Protection Agency  
1445 Ross Avenue  
Dallas, Texas 75202-2733

Kathleen O'Reilly (6H-CX)  
United States Environmental  
Protection Agency  
1445 Ross Avenue  
Dallas, Texas 75202-2733

Boyd Hamilton  
State of New Mexico  
Environmental Improvement Division  
Harold Runnels Bldg.  
1190 St. Francis Drive  
Santa Fe, New Mexico 87503



Subject: Monthly Progress Report 14  
General Electric Consent Decree  
Civil Action No. 87-1073-jb

Percentage of RFI Workplan completed - 99%.

Awaiting the results of the EPA review of the DRAFT RCRA FACILITY INVESTIGATION Report.

The non-regulated bentonite drilling mud resulting from the installation of the piezometers and monitoring wells will be solidified with fly-ash and removed from the site to disposal at a landfill for non-hazardous wastes.

Very truly yours,

Barry York  
Environmental Project Manager

/albuq14.wp

cc: Office of Regional Counsel, USEPA, 1445 Ross Ave., Dallas, Texas  
75202-2733  
AD Alcott, Law Environmental, Inc., 112 Townpark Drive, Kennesaw, GA.  
30144-5599  
PRC Environmental Management, Inc., American Financial Center, Bldg.4  
Suite 225, 2400 Louisiana Blvd. NE, Albuquerque, NM 87110  
JT Harrsen, GE, Albany  
CA Taylor, GE, Schdy.  
WP Thornton, GE, Schdy.