



Apparatus Service Department
General Electric Company
1 River Road, Bldg. 6, 2nd Floor
Schenectady, NY 12345
Building 6, Room 211
Tel. (518)-385-0545



October 10, 1990

Section Chief, Technical Section (6H-CX)
RCRA Enforcement Branch (6H-C)
United States Environmental
Protection Agency
1445 Ross Avenue
Dallas, Texas 75202-2733

Kathleen O'Reilly (6H-CX)
United States Environmental
Protection Agency
1445 Ross Avenue
Dallas, Texas 75202-2733

Boyd Hamilton
State of New Mexico
Environmental Improvement Division
Harold Runnels Bldg.
1190 St. Francis Drive
Santa Fe, New Mexico 87503

Subject: **Monthly Progress Report 15**
General Electric Consent Decree
Civil Action No. 87-1073-jb

Percentage of RFI Workplan completed - 99%.

The Quarterly Quality Assurance Report for the RCRA Facility Investigation was submitted.

The non-regulated bentonite drilling mud resulting from the installation of the piezometers and monitoring wells was solidified with fly-ash and removed from the site to disposal at a landfill for non-hazardous wastes.

The Final RFI Report will be submitted during the next reporting period.

Very truly yours,
Barry York
Barry York
Environmental Project Manager

albuq15.wp

cc: Office of Regional Counsel, USEPA, 1445 Ross Ave., Dallas, Texas
75202-2733
AD Alcott, Law Environmental, Inc., 112 TownPark Drive, Kennesaw, GA.,
30144-5599
PRC Environmental Management, Inc., American Financial Center, Bldg.4,
Suite 225, 2400 Louisiana Blvd. NE, Albuquerque, NM 87110
JT Harrsen, GE, Albany
CA Taylor, GE, Schdy.
WP Thornton, GE, Schdy.