



Apparatus Service Department
General Electric Company
1 River Rd., Bldg. 6, 2nd Floor, Schenectady, NY 12345

January 11, 1990

Tel. (518)-385-0545

Section Chief, Technical Section (6H-CX)
RCRA Enforcement Branch (6H-C)
United States EPA
1445 Ross Avenue
Dallas, Texas 75202-2733


Vincent Mallot, (6H-CX)
United States EPA
1445 Ross Avenue
Dallas, Texas 75202-2733

Boyd Hamilton
State of New Mexico
Environmental Improvement Division
1190 St. Francis Drive\Harold Runnels Bldg.
Santa Fe, New Mexico 87503

**SUBJECT: Quality Assurance Report
General Electric Consent Decree
Civil Action No. 87-1073-jb**

The Quality Assurance Report submitted in October, 1990, completed the evaluation of the data obtained to-date.

It is anticipated that additional soil samples will be collected in the next four weeks to evaluate constituents in the vicinity of Drywell No. 2. At that time we will make an evaluation of the attainment of the data quality objectives, review for compliance with procedures for data collection and evaluation, and determine any variances from the QA/QC plan. If there are any detrimental effects associated with any such variance they will be reported along with appropriate corrective measures. The results of these activities will be included in the next quarterly quality assurance report.

Very truly yours,

Barry R. York
Environmental Project Manager

albuqqr.wp

cc: Office of Regional Counsel, USEPA, 1445 Ross Ave., Dallas, Texas
75202-2733
AD Alcott, Law Environmental, Inc., 112 Townpark Drive, Kennesaw, GA,
30144-5599
PRC Environmental Management, Inc., American Financial Center, Bldg. 4,
Suite 225, 2400 Louisiana Blvd. NE, Albuquerque, NM 87110
JT Harrsen, GE, Albany
CA Taylor, GE, Schdy.
WP Thornton, GE, Schdy.