



Steve

GE Apparatus Service

General Electric Company
1 River Road
Schenectady, NY 12345



March 10 1993

518 385 0545


Section Chief, Technical Section (6H-CX)
RCRA Enforcement Branch (6H-C)
United States EPA
1445 Ross Avenue
Dallas, Texas 75202-2733

Vincent Malott, (6H-CX)
United States EPA
1445 Ross Avenue
Dallas, Texas 75202-2733

Boyd Hamilton
State of New Mexico
Environmental Improvement Division
1190 St. Francis Drive\Harold Runnels Bldg.
Santa Fe, New Mexico 87503

Subject: **Monthly Progress Report 44**
General Electric Consent Decree
Civil Action No. 87-1073-jb

Percentage of RFI completed - 100%
Percentage of CMS completed - 100%
Percentage of CMI completed - 25%



The EPA is reviewing the revised Final Corrective Measures Study submitted on April 29.

The four piezometers at the site were abandoned in accordance with the regulations of the State of New Mexico and comments received from the EPA.

Very truly yours,

Barry R. York
Environmental Project Manager

albuq44.wp

cc: Office of Regional Counsel, USEPA, 1445 Ross Ave., Dallas, Texas 75202-2733
AD Alcott, Law Environmental, Inc., 112 Townpark Drive, Kennesaw, GA., 30144-5599
PRC Environmental Management, Inc., 2021 Girard Blvd. SE, Suite 250, Albuquerque, NM 87106
JT Harrsen, GE, Albany
C. Allen, GE, Schdy.
WP Thornton, GE, Schdy.