



01 March 2006

Ms. Rita K. Ware, Environmental Scientist  
Compliance Assurance and Enforcement Division (6EN-HX)  
RCRA Hazardous Waste – Technical Section  
United States Environmental Protection Agency  
1445 Ross Avenue  
Dallas, Texas 75202

**SUBJECT:** Monthly Progress Report – February 2006  
Former GE Albuquerque Apparatus Inspection & Repair Service Center  
4420 McLeod Road, North East, Albuquerque, New Mexico  
General Electric Consent Decree, Civil Action No. 87-1073-jb

Dear Ms. Ware:

On behalf of GE Energy (GE), AMEC Earth & Environmental, Inc. (AMEC) has prepared and submits this February 2006 Monthly Status Report for the above referenced facility. During December 2005, remedial activities at the site have continued pursuant to 1) the final *Revised Closure Plan, Final Corrective Measure Study Report, Preliminary Corrective Measure Implementation Work Plan* (20 May 2003) and 2) subsequent pre-implementation investigations (detailed in the *Supplementary Investigation Work Plan* (25 March 2005) and *Supplementary Investigation Letter Report* (29 June 2005)). A more detailed description of the activities performed during February 2006 at the former Apparatus Inspection and Repair Service Center located in Albuquerque, New Mexico is detailed in the paragraphs below.

During February 2006, GE, AMEC, and Phillip Services Corporation of Phoenix, Arizona (PSC) continued remedial action at the site. Between 01 and 28 February 2006 the remedial tasks performed consist of the following:

- Continued to provide employee training pursuant to the Site-specific Health and Safety Plan;
- Maintained and decommissioned the established, site-specific areas for working in and handling the wastes generated, including the exclusion and decontamination zones, the limits and depths of excavations, and staging areas for the wastes generated on site;
- Hauled the remaining two (2) roll-off bins filled with wastes to the US Ecology Facility located in Beatty, Nevada;

AMEC Earth & Environmental, Inc.  
8519 Jefferson NE  
Albuquerque, NM 87113  
Tel (505) 821-1801  
Fax (505) 821-7371  
[www.amec.com](http://www.amec.com)

Ms. Rita Ware  
USEPA Region 6  
February 2006 Progress Report  
GE Energy - Former Service Center  
4420 McLeod Road NE  
Albuquerque, New Mexico  
Page 2 of 2



There is no remaining corrective measures fieldwork at the site. Pursuant to the 20 May 2003 Corrective Measures Implementation (CMI) Workplan, AMEC, on behalf of GE, is preparing a draft CMI Report for your review and comment. Pursuant to the approved schedule in the CMI workplan, the draft report will be delivered to you by Monday, 10 April 2006. Additional tasks planned for the site consist of plugging and abandoning the four (4) groundwater monitoring wells. This task will be performed following approval of the draft CMI Report.

AMEC will continue to submit monthly status reports to the USEPA and NMED for this project. More detailed information or copies of daily reports, inspection reports, laboratory/monitoring data, etc., are available for review at any time upon request by either the USEPA or NMED.

Please contact either Tom Antonoff of GE at (518) 385-9931 or the undersigned at (505) 821-1801 if you have any questions or concerns regarding this information.

Best Regards,

AMEC Earth and Environmental, Inc.

A handwritten signature in black ink, appearing to read "Peter A. Guerra".

Peter Guerra  
Project Manager

A handwritten signature in black ink, appearing to read "Bertisabel M. Custer".

Bertisabel M. Custer, CHMM  
Program Manager

cc: Mr. Thomas Antonoff, GE – Schenectady, New York  
Mr. Brian Salem – NMED