

GE



BILL RICHARDSON
Governor

DIANE DENISH
Lieutenant Governor

NEW MEXICO
ENVIRONMENT DEPARTMENT

Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1

Santa Fe, New Mexico 87505-6303

Phone (505) 476-6000 Fax (505) 476-6030

www.nmenv.state.nm.us



RON CURRY
Secretary

CINDY PADILLA
Deputy Secretary

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

September 7, 2007

Thomas D. Antonoff
GE Energy
1 River Road
Schenectady, New York 12345-6789

RE: NOTICE OF APPROVAL: CORRECTIVE ACTION COMPLETE, FORMER GE ALBUQUERQUE APPARATUS INSPECTION & REPAIR SERVICE CENTER, 4420 MCLEOD ROAD NORTHEAST, ALBUQUERQUE, NEW MEXICO GE ENERGY, EPA ID# NMD047140256 HWB-GE-06-001

Dear Mr. Antonoff:

The New Mexico Environment Department (NMED) has reviewed the Final Corrective Measures Implementation and Construction Certification Report dated September 28, 2006. The NMED concurs with the U. S. Environmental Protection Agency (EPA) that the Report fulfills the corrective measures required by the Consent Decree No. 87-1073-JB to conduct a soil and ground water investigation, close the dry wells and leach field and perform corrective action as required.

Therefore, the NMED deems the corrective action activities complete at the Former GE Apparatus Service Center, 4420 McLeod NE, Albuquerque.

Mr. Antonoff
September 7, 2007
Page 2

If you have any questions regarding this matter, please contact Brian L. Salem of my staff at (505) 222-9576.

Sincerely,



James P. Bearzi
Chief
Hazardous Waste Bureau

cc: J. Kieling, NMED HWB
W. Moats, NMED HWB
L. King, US EPA Region 6 (6PD-N)
R. Ware, US EPA Region 6 (6PD-N)
File: GE 2007 and Reading
GE-06-001