



ENTERED

MICHELLE LUJAN GRISHAM
GOVERNOR

JAMES C. KENNEY
CABINET SECRETARY

Certified Mail - Return Receipt Requested

July 23, 2021

Colonel David S. Miller
Base Commander
377 ABW/CC
2000 Wyoming Blvd SE
Kirtland AFB, NM 87117

Lt. Colonel Wayne J. Acosta
Civil Engineer Office
377 Civil Engineering Division
2050 Wyoming Blvd SE, Suite 116
Kirtland AFB, NM 87117

**RE: STATUS UPDATE – INVESTIGATION WORK PLAN AND INVESTIGATION REPORTS
FOR MULTIPLE SWMUS
KIRTLAND AIR FORCE BASE, NEW MEXICO
EPA ID # NM9570024423
HWB-KAFB-21-MISC**

Dear Colonel Miller and Colonel Acosta:

The New Mexico Environment Department (NMED) received the U.S. Air Force (Permittee) Kirtland Air Force Base (Facility) Environmental Assessment (EA) of Re-entry Vehicle Integration Laboratory (REVL) Facilities for AFLR (EA), on May 6, 2021. During the review for the EA, several SWMUs were found to be located near the proposed new facilities. These include SWMU 10-21-B, ST-291, Septic System Bldg. 617, SWMU 10-21-B, ST-289, Septic System Bldg. 617 & 620, SWMU 10-21-B, ST-288, Septic System Bldg. 614, and SWMU 10-21-D ST-299, Septic System Bldg. 751. These nearby SWMUs, as well as numerous other SWMUs, were listed in Table I-3, Solid Waste Management Units (SWMUs) and Areas of Concern (AOCs) Requiring Corrective Action in the Facility Operating Permit as requiring an Investigation Report.

NMED does not have a record of receiving either an Investigation Work Plan (WP) or an Investigation Report in its Administrative Record for the following SWMUs listed in the table below.

SCIENCE | INNOVATION | COLLABORATION | COMPLIANCE

Hazardous Waste Bureau - 2905 Rodeo Park Drive East, Building 1, Santa Fe, New Mexico 87505-6313
Telephone (505) 476-6000 - www.env.nm.gov

KAFB5050



SWMU	IRP Site	Site Name	Requirement	Due Date
6-4	LF-008	LF-008 Selenium in GW	Investigation WP	3/31/2011
10-21-B	ST-288	Septic System Bldg 614	Investigation Report	12/31/2012
10-21-B	ST-289	Septic System Bldg 617 & 620	Investigation Report	12/31/2012
10-21-B	ST-291	Septic System Bldg 617	Investigation Report	12/31/2012
10-21-C	ST-294	Septic System Bldg 633	Investigation Report	12/31/2012
10-21-C	ST-298	Septic System Bldg 730 & 734	Investigation Report	12/31/2012
10-21-C	ST-299	Septic System Bldg 751	Investigation Report	12/31/2012
10-21-P	ST-312	Septic System Plant 2 & Bldg 37503	Investigation Report	12/31/2012
10-21-S	ST-314	Septic System Bldgs 48056 & 48059	Investigation Report	12/31/2012
10-21-T	ST-316	Septic System CERF Bldgs 57001 & 57002	Investigation Report	12/31/2012
10-21-AA	ST-333	Septic System SOR Bldg 66001	Investigation Report	6/30/2013
10-21-AA	ST-343	Septic System SOR Bldg 66000 & 66008	Investigation Report	6/30/2013
10-21-AA	ST-344	Septic System SOR Bldg 66042	Investigation Report	6/30/2013

NMED requests the Permittee identify when the documents were submitted, submit the relevant Work Plans or Investigation Reports by **September 30, 2021**, or explain why they have not yet been submitted. Note that any extension requests for these documents must be accompanied by a justification for the extension(s) and a request for a Class 1 Permit Modification.

If you have any questions regarding this letter, please contact Naomi Davidson at (505) 690-7567.

Sincerely,

Ricardo Maestas Digitally signed by Ricardo Maestas
Date: 2021.07.22 11:56:54 -06'00'

Ricardo Maestas
Acting Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
N. Davidson, NMED HWB
B. Wear, NMED HWB
L. King, EPA Region 6 (6LCRRC)
S. Clark, KAFB

File: KAFB 2021 and Reading