

# APOGEN TECHNOLOGIES

1350 Central Avenue, Suite 300  
Los Alamos, NM 87544

## Memo:

**To:** File  
**From:** Candace Christensen  
**CC:**  
**Date:** March 24, 2008  
**Re:** Visual inspection of SWMU 60-002 (west)

---

On March 19, 2008, Candace Christensen of Apogen Technologies visually inspected SWMU 60-002 (west) from the dirt road running along the southern edge of the SWMU. The SWMU area was not fenced and contained heavy equipment including trailers, a crane, rolloff bins, a sheep's foot roller, a truck, and a liquid nitrogen tank. Construction debris was also observed within the SWMU area. The area on the north side of the SWMU historically contained a large mound of soil and construction debris. The dirt mound has been removed and the area is now fenced and appears to be approximately a foot below grade of the SWMU. This fenced area contained a large dumpster and wooden reels containing conduit and wire or tubing. The area south of the SWMU across the dirt road contained construction debris and some additional trailers.

