



[Return To Library](#) > [Records 2](#) > [ERID-105000 Through ERID-105499](#) > [ERID-105232](#) 1) CERTIFICATION OF CLOSURE, TA-36 SANITARY LANDFILL WITH MDA AA MAP. 2) PHOTO: LOOKING EAST TO AREA AA, TA-36 PRIOR TO CLOSURE. 3) PHOTO: LOOKING WEST TO AREA AA, TA-36 PRIOR TO CLOSURE. 4) PHOTO: LOOKING AT SCRAP LUMBER AT AREA AA, TA-36 PRIOR TO CLOSURE. 5) PHOTO: LOOKING EAST AT AREA AA, TA-36 AFTER CLOSURE 6) PHOTO: LOOKING WEST AT AREA AA, TA-36 AFTER CLOSURE 7) PHOTO: LOOKING WEST AT AREA AA, TA-36 AFTER CLOSURE

Created By: Nicola M. Valerio/STERS/LANL
 File name: Target-ERID-#-for-Domino.txt
 Version: 2.0
 Document Type: RPF Record
 Description: SUBMITTED BY: PHOEBE K. SUINA,
 CORRECTIVE ACTIONS.
 REFERENCE CITED

Document Details:

Title: ERID-105232 1) CERTIFICATION OF CLOSURE, TA-36 SANITARY LANDFILL WITH MDA AA MAP. 2) PHOTO: LOOKING EAST TO AREA AA, TA-36 PRIOR TO CLOSURE. 3) PHOTO: LOOKING WEST TO AREA AA, TA-36 PRIOR TO CLOSURE. 4) PHOTO: LOOKING AT SCRAP LUMBER AT AREA AA, TA-36 PRIOR TO CLOSURE. 5) PHOTO: LOOKING EAST AT AREA AA, TA-36 AFTER CLOSURE 6) PHOTO: LOOKING WEST AT AREA AA, TA-36 AFTER CLOSURE 7) PHOTO: LOOKING WEST AT AREA AA, TA-36 AFTER CLOSURE

ERID Number.StartPage: ERID-105232

Office of Record: WES-DO

Date Received: 03/30/2009

Official Use Only: N

Page Count: 8

Record Type: Photo

Document Date: 05/12/89

To:(Addressees - Organization) N/A
(separate multiple values with semicolons)

From:(Senders - Organization) LOS ALAMOS NATIONAL LABORATORY
(separate multiple values with semicolons)

Other Document Number(s): PKG-1827
 ENG-R-4482
 JOB NUMBER 1157
 TA: 36
(separate multiple values with semicolons)

PRS Number(s): N/A
(separate multiple values with semicolons)

Record Box Number:

* Denotes Fields that are mandatory.

To download this file, right mouse click on the file

[Target-ERID # for Domino.txt](#) <-- This link points to this version.

To check-out and/or edit this file, select Edit Document or Check Out

31613



LANL Environmental Programs (EP) Directorate, Record Transmittal Form

PRINT

To complete this form, see instructions on following pages. Use continuation version of form to list more records. See EP-DIR-SOP-4004 for more information.

Transmittal date: 03/26/2009 Priority Processing? Yes No Official Use Only? Yes No UCN? Yes No Page 1 of 1

Reference Cited in NMED Deliverables? Yes No Receipt Acknowledgement: Do you need this form returned to you? Yes No

Transmitter Information

Z #: 177374 Name: Phoebe K. Suina E-mail: phoebe@lanl.gov Transmitters Organization: WES-DO

Contamination Potential

To the best of my knowledge, the record(s) has no radioactive contamination. Signature: *Phoebe K. Suina*

Record Type: Individual Record New package E-mail Add to existing package (fill in # and title below) Resubmitted/superseded record (record #)

Package(s) #: _____ Package title(s): _____

Reference/Retrieval Information

Organization: Corrective Actions – PKG # 1827

Record (Package) Contents						
Record Title	Media Type	Document Date	Author/Originator	Other Doc. # (e.g. Doc. Catalog #)	Page Count	ERID (RPF only)
Certification of Closure, TA-36 Sanitary Landfill with MDA AA map	Paper (letter)	06/26/1989	Steven R. Rae, LANL	N/A	2	10523Z
Photo: Looking East to Area AA, TA-36 Prior to Closure (double-sided)	Photo	05/01/1989	Los Alamos National Laboratory	N/A	2	↑
Photo: Looking West to Area AA, TA-36 Prior to Closure (double-sided)	Photo	05/01/1989	Los Alamos National Laboratory	N/A	2	
Photo: Looking at Scrap Lumber at Area AA, TA-36 Prior to Closure (double-sided)	Photo	05/01/1989	Los Alamos National Laboratory	N/A	2	

RPF Use Only: (names and dates) Accepted *MS* Entered *MS* 3/30/09 Scanned | QC: _____

Click here for Continuation Form

LANL Environmental Programs (EP) Directorate, Record Transmittal Continuation Form

PRINT

Page 2 of 2

Previous package #: _____ or new package title: _____

Record (Package) Contents

Record Title	Media Type	Document Date	Author/Originator	Other Doc. # (e.g. Doc. Catalog #)	Page Count	ERID (RPF only)
Photo: Looking East at Area AA, TA-36 After Closure (double-sided)	Photo	05/12/1989	Los Alamos National Laboratory	N/A	2	
Photo: Looking West at Area AA, TA-36 After Closure (double-sided)	Photo	05/12/1989	Los Alamos National Laboratory	N/A	2	
Photo: Looking West at Area AA, TA-36 After Closure (double-sided)	Photo	05/12/1989	Los Alamos National Laboratory	N/A	2	

RPF Use Only: (names and dates)

Accepted

Entered

Scanned

QC:


Certification of Closure

TA-36 Sanitary Landfill
Los Alamos National Laboratory

I hereby certify that the TA-36 Sanitary Landfill also known as Area AA at Los Alamos National Laboratory was closed and covered on May 12, 1989, in accordance with the New Mexico Solid Waste Management Regulations dated April 19, 1974.

JUNE 26, 1989



Date



Steven R. Rae, P.E.

RECEIVED
MAR 30 2009

BY: W.



NO.	DATE	CLASS.	BY	BY	DATE	BY	DATE	BY	DATE
REVISIONS AND ANY CHANGES APPROVED BY:									
THIS JOB MUST BE INSPECTED AND ANY CHANGES APPROVED BY:									
ENG. 4 PHONE:									
LOS ALAMOS SCIENTIFIC LABORATORY ENGINEERING DEPARTMENT UNIVERSITY OF CALIFORNIA - LOS ALAMOS, NEW MEXICO									
PWG CLASSIFICATION: <i>U</i> <i>SECRET</i> TITLE: <i>H. E. BURNING PITS</i>									
AUTHORIZED FOR:									
SECURITY:									
SAFETY:									
HEALTH:									
DIVISION:									
GROUP:									
CHECKED: <i>R. A. ...</i> DATE:									
DESIGNED: <i>T. G. ...</i> DATE:									
DRAWN: ROYAL 1757									
APPROVED: <i>U. M. D. Keller</i> DATE:									
TA - 36									
MATERIALS DISPOSAL AREAS AREA "AA"									
ENG-R-4492									

NOT FOR CONSTRUCTION
 THIS DRAWING IS THE PROPERTY OF
 LOS ALAMOS SCIENTIFIC LABORATORY
 AND IS NOT TO BE REPRODUCED OR
 TRANSMITTED IN ANY FORM OR BY
 ANY MEANS, ELECTRONIC OR MECHANICAL,
 INCLUDING PHOTOCOPYING, RECORDING,
 OR BY ANY INFORMATION STORAGE AND
 RETRIEVAL SYSTEM.



105232

Los Alamos
Los Alamos National Laboratory
Los Alamos, New Mexico 87545
Photography

Looking west to Area AA,
TA-36 prior to closure
May 1, 1989



105232

LOS ALAMOS
Los Alamos Neutron Laboratory
Los Alamos, New Mexico 87545
Photography

Looking east to Area AA,
TA-36 prior to closure,
May 1, 1989



105232

Ecology Department Laboratory
Los Angeles, New Mexico 87545
Los Angeles, New Mexico 87545
Photography

Looking at Scrap Lumber
of Area AA, TA-36
May 1, 1989



105232

Looking west at Area AA,
TA-36 after closure
May 12, 1988

Los Alamos
Los Alamos National Laboratory
Los Alamos, New Mexico 87545
Photography



105232

Los Alamos
Los Alamos National Laboratory
Los Alamos, New Mexico 87545
Photography

Looking west at Area AA,
TA-36 after closure
May 12, 1989



105232

Looking east at Area AA,
TA-36 after closure
May 12, 1989

Los Alamos
Environmental Laboratory
37545
Photography