



Department of Energy
Albuquerque Operations
Los Alamos Area Office
Los Alamos, New Mexico 87544

AUG 28 1991

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. Coby Muckleroy
New Mexico Environment Department
Hazardous and Radioactive Waste Bureau
Harold Runnels Building
1190 St. Francis Dr., P. O. Box 26110
Santa Fe, NM 87502



Dear Mr. Muckleroy:

REFERENCE: REQUEST FOR PHOTOGRAPHS TAKEN DURING THE APRIL 29
THROUGH MAY 3, 1991, HAZARDOUS WASTE INSPECTION

Enclosed are the requested copies of photographs taken by the Los Alamos National Laboratory (LANL) staff during the LANL hazardous waste inspection. If you have any questions, or need additional photographs, please contact Mr. Steve Slaten of my staff at 665-5050 (FTS/843-5050).

Sincerely,

Monet C. Harrison, Acting Chief
Environment, Safety & Health Branch

LESH:1MH-010


Enclosure

cc:

John Puckett, HSE-DO, LANL, MS-K491
Tom Gunderson, HSE-DO, LANL, MS-K491
Ken Hargis, HSE-8, (HSE-8:91-1073-1),
LANL, MS-K490
Jim White, HSE-8, LANL, MS-K490
Circ. File



16532




Arrow points to nested can with unknown solid waste

TA-21-3N-Outside Room 361

CM



SA 9 which should be managed as a 60 day
TA-3 Structure 1767 Storage area.
Several containers inside the structure
had no accumulation dates. (CM)



One container stored > 90 days
one container with no accumulation date (CM)

TA-35-85


Drum of rags contain solvent labelled as "Non-Reg-ulated waste"



see above notes


TA-3-1767

CM




TA-50-1 Less Than 90 Day Storage

No accumulation start date *cn*




No insp. logs are maintained for these
TA-53 North East Lagoon
mixed waste lagoons.
Also, they do not meet MTR. *(CN)*



see notes at right. *cn*

TA-53 North West Lagoon



see above notes. *cn*

TA-53 South Lagoon