

LIST OF DEFICIENCIES
LANL VCA COMPLETION REPORT FOR
PRS 0-016

1. Page 14, 2nd paragraph: It states, "Twenty-two metal detector responses were determined by correlation to indicate a total lead concentration of 396 mg/kg, which is nearly equivalent to the current SAL of 400 mg/kg." The reviewer is unclear how LANL reaches the correlation. Please explain. **(Best Professional Judgement (BPJ))**

2. Page 20, 1st paragraph: It states, "A summary of utility right-of-way samples is provided in Table 3.3.2-2." However, the table is omitted from the report. Where are the sample locations and the sample identification numbers for these four confirmation samples collected from the eastern edge of the PRS boundary? **(BPJ)**

3. Page 20, Section 3.3.3 First-Order Drainage Confirmatory Sampling: It states, "Locations of channel sediment samples are shown on Figure 3.3-1. A summary of these samples is presented in Table 3.3.3-1" Please explain
 - a. Where is Table 3.3.3-1?
 - b. What are their sample identification numbers?
 - b. Where are these samples located in Figure 3.3-1?
 - c. What does "First-Order" drainage mean?
 - d. Where are the analytical results? **(BPJ)**