

Los Alamos

Environmental Restoration
Records Processing Facility



ER Record I.D.# 62921

**LOS ALAMOS NATIONAL LABORATORY
ENVIRONMENTAL RESTORATION
Records Processing Facility
ER Records Index Form**

ER ID NO. 62921 **Date Received:** 4/7/99 **Processor:** YCA **Page Count:** 4

Privileged: (Y/N) N **Record Category:** P **Record Package No:** 0

FileFolder: N/A

Correction: (Y/N) N **Corrected No.** 0 **Corrected By Number:** 0

Administrative Record: (Y/N) Y

Refilmed: (Y/N) N **Old ER ID Number:** 0 **New ER ID Number:** 0

Miscellaneous Comments:

REFERENCE CITED



7243

(4)

62921

To Jim Aldrich, MS M992

10/18/93

From Miguel Salazar 

Subject: HRL Line Removal in March 1991

Attached is a field survey that indicates we removed 26 feet of the line starting from the face of HRL-1. The opening at the building and the exposed pipe at the 26 feet disconnect end were capped with concrete. This remaining line runs easterly to a manhole and parking lot. Note that the remaining acid sewer line was not removed due to restrictions on the interim action to perform removal of line that was only necessary to complete the construction of the HRL addition and rerouted of utility lines in this area. If you need additional information please call me. 53056

WAS TOP COAT W/LL ASSUMED.
APPROX TOP OF PIPE
@ BLDG LINE

4' 8" 1/2
8' 8" 1/2
8' 8" 1/2
4' 8" 1/2

N 117° 21' E
26.4 FT
N 45° 21' E
26.4 FT
GAS WATER
INDUSTRIAL
N 1010.04
E 8860.5


N 1021.7
E 5858.9
LOCATED BY CAD
N 1015.7
E 5851.9
FL 88.4
2013 CO. WALL
N 993.8
E 5858.9

NOTE: END OF PIPE AS

EAST END of General as shown to ESUR BY CAD.
NOTE: No visible evidence of pipe and was buried.
Trench was badly SLOUGHED. NO BL. AVAILABLE
N 1021.1
E 5880.2


1000 N
6000 E ASSU

SEE SECTION
N 771.0
E 5710.7



ASSUMED

TA-43 HRL
WO # 5840017
EVENT E4580
By ESDR



4

ER ID

Memo from Miguel Salazar regarding removal of west end of Line 170.

APR 07 1999
CMA