



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


REGION 6  
1445 ROSS AVENUE, SUITE 1200  
DALLAS, TX 75202-2733

*Rank*  
*Teri*  
*Barbara*

NOV 29 1994

Mr. Theodore J. Taylor  
Program Manager  
Environmental Restoration Program  
Department of Energy  
Los Alamos National Laboratory  
Los Alamos, NM 87544

*included?*  
*04/11/94*



Dear Mr. Taylor:

During recent sampling conducted at Solid Waste Management Unit (SWMU) 3-010(a), ground water was encountered in the form of a perched aquifer. The Environmental Protection Agency (EPA) would like to be informed in the future of any occurrences where ground water is unexpectedly encountered during sampling or coring at any site. EPA may request sampling and analysis of the ground water, or installation of a monitoring well.

Should you have any questions, please contact me at (214) 665-7441.

Sincerely,

*Barbara Driscoll*

Barbara Driscoll, Geologist  
NM/Federal Facilities Section

cc: Mr. Benito Garcia ✓  
Bureau Chief, Hazardous and Radioactive Materials Bureau  
New Mexico Environment Department  
Mr. Jorg Jansen  
Program Manager, Environmental Restoration Program  
Los Alamos National Laboratory, M992

*TV*



5450