

TA 03



*Environmental Stewardship Division (ENV-DO)*  
*Water Quality & Hydrology Group (ENV-WQH)*  
P.O. Box 1663, Mail Stop K497  
Los Alamos, New Mexico 87545  
(505) 665-1859/FAX: (505) 665-9344

Date: March 16, 2005  
Refer To: ENV-WQH: 05-048



Ms. Kathryn Chamberlain  
Environmental Scientist  
Hazardous Waste Bureau  
New Mexico Environment Department (NMED)  
2905 Rodeo Park Drive East, Bldg. 1  
Santa Fe, NM 87505-6303

**SUBJECT: CHARACTERIZATION REPORT REGARDING DIESEL CONTAMINATED SOIL NEAR THE TA-3-26 ABOVEGROUND STORAGE TANK (AST)**

Dear Ms. Chamberlain:

Enclosed is a copy of the "TA-3-26 Diesel Fuel Oil Contamination Assessment and Characterization" dated April 26, 2004, per your request. This report was originally submitted on May 5, 2004, to Carolyn Copper of NMED's Hazardous Waste Bureau.

Please contact Mark Haagenstad at (505) 665-2014 or Mike Saladen at (505) 665-6085 if additional information would be helpful. Please let us know if you would like to visit the site during your review.

Sincerely,

Steven Rae  
Group Leader  
Water Quality & Hydrology Group

SR:MH/lm



Enclosure: a/s

Cy: John Young, NMED/HWB, Santa Fe, NM, w/o enc.  
Lorena Goerger, NMED/PSTB, Santa Fe, NM, w/o enc.  
Steve Yanicak, NMED/OB, w/o enc., MS J993  
Gene Turner, NNSA/LASO, w/o enc., MS A316  
David Padilla, NWIS-UI, w/o enc., MS K718  
Jerome Gonzales, NWIS-UI, w/o enc., MS K718  
Kenneth Hargis, ENV-DO, w/o enc., MS J591  
Victoria George, ENV-DO, w/o enc., MS J591  
Doug Stavert, ENV-DO, w/o enc., MS J591  
Mike Saladen, ENV-WQH, w/o enc., MS K497  
Mark Haagenstad, ENV-WQH, w/o enc., MS K497  
Bruce Baumgartner, SSS-AE-V02, w/o enc., MS A199  
Phil Wardwell, LC-ESH, w/o enc., MS A187  
ENV-WQH File, w/enc., MS K497  
IM-5, w/enc., MS A150