


09

ENTERED



Environmental Protection Division
Water Quality & RCRA Group (ENV-RCRA)
P.O. Box 1663, K490
Los Alamos, New Mexico 87545
(505) 667-0666

National Nuclear Security Administration
Los Alamos Site Office, A316
3747 West Jemez Road
Los Alamos, New Mexico 87545
(505) 667-5794/FAX (505) 667-5948

Date: **APR 24 2012**
Refer To: ENV-RCRA-12-0087
LAUR: 12-20484

Mr. William M. Oberle
Regulatory Division
Albuquerque District, Corps of Engineers
4101 Jefferson Plaza NE
Albuquerque, NM 87109-3435

Dear Mr. Oberle:

SUBJECT: ACTION NO. SPA-2011-00464-ABQ, SECTION 404 NATIONWIDE PERMIT CERTIFICATION OF COMPLIANCE

On October 20, 2011, the U.S. Army Corps of Engineers provided after-the-fact authorization for the Los Alamos National Laboratory to conduct emergency culvert replacement at three locations in Cañon de Valle. In accordance with the General Conditions of Nationwide Permit No. 3, please find the following enclosures:

- **Enclosure 1**, signed *Certification of Compliance*, Action No. SPA-2011-00464-ABQ ; and
- **Enclosure 2**, photographs of recently installed headwalls at each replacement culvert.


The *Certification of Compliance* and photographs are being submitted to document the completion of work. Accordingly, we are requesting final closure of the above referenced permit.




Please contact Robert S. Beers by telephone at (505) 667-7969 or by email at bbeers@lanl.gov if you have questions regarding this information.

Sincerely,

Sincerely,



Alison M. Dorries
Division Leader
Environmental Protection Division
Los Alamos National Security, LLC



Gene E. Turner
Environmental Permitting Manager
Environmental Projects Office
Los Alamos Site Office
U.S. Department of Energy

AMD:GET:BB/lm

Enclosures:

1. *Certification of Compliance*, Action No. SPA-2011-00464-ABQ
2. Photographs of replacement culvert headwalls

Cy: James P. Bearzi, NMED/SWQB, Santa Fe, NM, w/enc.

John E. Kieling, NMED/HWB, Santa Fe, NM, w/enc.

Steve M. Yanicak, NMED/DOE/OB, w/enc., M894

Hai Shen, LASO-EPO, w/enc., A316

Gene E. Turner, LASO-EPO, w/enc., A316

Carl A. Beard, PADOPS, w/o enc., A102

Michael T. Brandt, ADESH, w/o enc., K491, (E-File)

Alison M. Dorries, ENV-DO, w/o enc., K491, (E-File)

Andrew W. Erickson, UI-DO, w/o enc., K760, (E-File)

Michael T. Saladen, ENV-RCRA, w/o enc., K490, (E-File)

Lawrence V. Chavez, UI-OPS, w/enc., K760, (E-File)

Marjorie B. Stockton, ENV-ES, w/enc., K760, (E-File)

Robert S. Beers, ENV-RCRA, w/enc., K490

IRM-RMMSO, w/enc., A150, locatsteam@lanl.gov

ENV-RCRA Correspondence File, w/enc., K490

ENCLOSURE 1

Certification of Compliance, Action No. SPA-2011-00464-ABQ

ENV-RCRA-12-0087

LAUR-12-20484

Date: APR 24 2012

**Certification of Compliance
with Department of the Army Nationwide Permit**

Action Number: SPA-2011-00464-ABQ

Name of Permittee: Robert Beers, Los Alamos National Laboratory

Nationwide Permit: 3 for Maintenance

Project Location: Canon de Valle, 3 Replacement Culverts

Upon completion of the activity authorized by this permit and any mitigation required by the permit, sign this certification and return it to the following address:

Mr. William Oberle
Albuquerque District, U.S. Army Corps of Engineers
4101 Jefferson Plaza NE
Albuquerque, NM 87109-3435
505-342-3284
FAX 505-342-3498

Please note that your permitted activity is subject to a compliance inspection by an U.S. Army Corps of Engineers representative. If you fail to comply with this permit, you are subject to permit suspension, modification, or revocation.


Please enclose photographs showing the completed project (if available).

I hereby certify that the work authorized by the above referenced permit has been completed in accordance with the terms and conditions of the said permit, and required mitigation was completed in accordance with the permit conditions.

Date Work Started 12/12/2011

Date Work Completed 3/16/2012

4/10/12
Date


Signature of Permittee

ENCLOSURE 2

Photographs of replacement culvert headwalls

ENV-RCRA-12-0087

LAUR-12-20484

Date: APR 24 2012

ENCLOSURE 2



Photograph 1. Upstream headwall, Cañon de Valle road crossing to the TA-16 borrow pit.



Photograph 2. Upstream headwall, Cañon de Valle/Anchor Ranch Road crossing.

ENCLOSURE 2



Photograph 3. Upstream headwall, Cañon de Valle/perimeter fence crossing.