



ER Record I.D.# 0006789

LOS ALAMOS

LOS ALAMOS NATIONAL LABORATORY

ENVIRONMENTAL RESTORATION
Records Processing Facility
ER Record Index Form
(Side 1 of 2)

DATE RECEIVED: 07-17-92 PROCESSOR: LD

Part I: Complete all fields; indicate if not applicable or appropriate; please write legibly.

DOCUMENT TO: J.E. RUSSO DOCUMENT DATE: 03/09/90

ORIGINATOR NAME: William R. Kennedy ORGANIZATION: H-6

SYMBOL: — PAGE COUNT: 1

SUBJECT/TITLE: Contaminated Survey: Buildings and Structures
TA-16

RECORD TYPE (Circle relevant type for primary record; type of attachments should be selected on Keywords List):

Analytical Data
Chain-of-Custody
Computer Output
Contract
Controlled Distribution
Drawing

FAK
Figure
Form
Interview
Letter
Logbook

Map
Memo
 MICROFORM
Notebook
Personal Notes
Photo

Plan
Procedure
Purchase Request
Receipt Acknowledgment
Reqs-1
Review

Study
Telephone Record
Transcription
Video
Work Plan
Other

RECORD CATEGORY: P

RECORD PACKAGE #: —

(P for Programmatic or R for Reference)

RECORD FILMED (Y/N): Y

RECORD LOCATION: —

(Indicate location of record if not filmed.)

Part II: Complete all fields; indicate if not applicable or appropriate; please write legibly. Use ER Record Index Form Attachment Sheet if needed.

ATTACHMENTS FILMED (Y/N): —

LOCATION: —

(Were attachments to this record filmed?)

(Indicate location of attachments.)

TECH AREAS

LIST RELEVANT TECH AREAS

16

PRS NO(S)

LIST RELEVANT PRS

—

ADS NO(S)

LIST RELEVANT THRUADS NOS

1082

STRUCTURE NOS/MSA

LIST RELEVANT STRUCTURE NOS/MSA

16-512
16-793
16-794
16-795
16-796
16-797
16-798
16-799
16-89
16-90 16-1129
16-91 16-1134
16-92 16-1135
16-93
16-27
16-390



①
OFFICE MEMORANDUM

TO : S. E. Russo, Group Leader, ENG-3

DATE: March 9, 1970
Em 3/9

FROM : William R. Kennedy, Group Leader, H-6

SUBJECT: CONTAMINATED SURVEY: BUILDINGS AND STRUCTURES, TA-16

SYMBOL : H-6

SB - your file on this subject -

Buildings TA-16-512 through 520 floor drains empty through (manholes, industrial wastes) structure numbers TA-16-793 through 799 into a relative flat area southeast of buildings. Water sample collected at end of drain line contained no detectable radioactive contamination (gross alpha or beta emitters).

Buildings TA-16-89 through 93 floor drains empty into earth tank west of buildings. Water sample collected from tank contained no detectable gross alpha emitters and only a trace of gross beta emitters.

Building TA-16-27 contained only sanitary sewer service to sewage treatment plant. No water sample collected.

Building TA-16-390 floor drains empty through structure numbers TA-16-1129, TA-16-1134, and TA-16-1135 (troughs) into burning vat. No water present.

As a result of our survey there appears to be no environmental hazard due to radioactivity.

William R. Kennedy

William R. Kennedy

WDP:WRK:mtj

CC: D. D. Meyer, H-1
Roy Reider, H-3
H. F. Schulte, H-5

Received by ER-RMF

JUL 17 1970

Itom