

Los Alamos

Environmental Restoration
Records Processing Facility



ER Record ID # 0005790

LOS ALAMOS

LOS ALAMOS NATIONAL LABORATORY

ENVIRONMENTAL RESTORATION
Records Processing Facility
ER Record Index Form
(Side 1 of 2)

DATE RECEIVED: 07-17-92 PROCESSOR: LID

Part I: Complete all fields; indicate if not applicable or appropriate; please write legibly.

DOCUMENT TO: A.L. Russo DOCUMENT DATE: 03/18/70

ORIGINATOR NAME: E.D. Mitchell ORGANIZATION: H-5

SYMBOL: - PAGE COUNT: 1

SUBJECT/TITLE: Contamination Survey: Building & Structure
TR-16

RECORD TYPE (Circle relevant type for primary record; type of attachments should be selected on Keywords List):

Analytical Data
Chain-of-Custody
Computer Output
Contract
Controlled Distribution
Drawing

FAX
Figure
Form
Interview
Letter
Logbook

Map
 Microform
Notebook
Personal Notes
Photo

Plan
Procedure
Purchase Request
Receipt Acknowledgment
Report
Review

Study
Telephone Record
Transcription
Video
Work Plan
Other

RECORD CATEGORY: P
(P for Programmatic or R for Reference)

RECORD PACKAGE #: _____

RECORD FILMED (Y/N): Y

RECORD LOCATION: _____
(Indicate location of record if not filmed.)

Part II: Complete all fields; indicate if not applicable or appropriate; please write legibly. Use ER Record Index Form Attachment Sheet if needed.

ATTACHMENTS FILMED (Y/N): -
(Were attachments to this record filmed?)

LOCATION: _____
(Indicate location of attachments.)

TECH AREA(S)

LIST RELEVANT TECH AREAS:

16

PRS NO(S)

LIST RELEVANT PRS:

-

ADS NO(S)

LIST RELEVANT TDS/ADS NO(S):

1082

STRUCTURE NO(S)/MBA

LIST RELEVANT STRUCTURE NO(S)/MBA:

16-27
16-93
16-384
16-390
16-391
16-793
16-794
16-795
16-796
16-797
16-798
16-799
16-1129
16-1134
16-1135



①
OFFICE MEMORANDUM

TO : S. E. Russo, Group ENG-3

DATE: March 18, 1970

FROM : R. N. Mitchell, Section Leader, Eng. Section

SUBJECT: CONTAMINATION SURVEY: BUILDING & STRUCTURE SURVEY, TA-16

SYMBOL : H-5

On March 13, 1970, a survey was made of the following structures:

- TA-16-27 Storage Bldg. No significant amount of toxic or chemical contamination.
- TA-16-93 Process Bldg. This building was used as an electroplating laboratory and can be considered to contain significant amounts of toxic and chemical contamination.
- TA-16-384 Cross-over Platform. No significant amount of toxic or chemical contamination.
- TA-16-390 Basketed Washing Bldg. No significant amount of toxic or chemical contamination.
- TA-16-391 Tank, Fuel. No significant amount of toxic or chemical contamination. The amount of fuel in the tank is not known.
- TA-16-793- Manholes & drains. Not individually inspected.
thru 799 The possibility of toxic or chemical contamination is insignificant.
- TA-16-1129 Troughs. No significant amount of toxic or chemical
1134-1135 contamination.

cp

cc: D. Meyer, H-1
R. Reider, H-3
W. Kennedy, H-6

Robert N. Mitchell
Robert N. Mitchell
Section Leader
Engineering Section
Industrial Hygiene Group

Processed by ER-RPF

JUL 17 1992

152