

New Mexico Environment Department Underground Storage Tank Bureau

1190 St. Francis Dr., Harold Runnels Bldg., Rm N2150
Santa Fe, NM 87502
(505) 827-0188
Fax: (505) 827-0310

FAX TRANSMISSION COVER SHEET

Date: 10/1/97
To: BARBARA TOTH - HRMB
Fax: 827-1544
Re: TA-21 Docs -

Sender: LORENA GOERGER - USTB

YOU SHOULD RECEIVE 3 PAGE(S), INCLUDING THIS COVER SHEET. IF YOU DO NOT RECEIVE ALL THE PAGES, PLEASE CALL (505) 827-0110

HERE ARE THE TWO DOCUMENTS I TOLD YOU ABOUT -
IF YOU HAVE ANY QUESTIONS GIVE ME A CALL.

A NOTE: A DIFFERENT TA-21 FACILITY NUMBER/LOCATION
WAS NFA'D IN 1993. BUT AS FAR AS I CAN
TELL IT WASN'T DEALING W/ DP CANYON +
THE SEEP THERE OR THE TANKS.

Lorina

HSWA LANK 1/1106/21



10314



GARY E. JOHNSON
GOVERNOR

State of New Mexico
ENVIRONMENT DEPARTMENT
Underground Storage Tank Bureau

Harold Runnels Building
1190 St. Francis Drive, P.O. Box 26110
Santa Fe, New Mexico 87602
(505) 827-0188
(505) 827-0310 Fax

MARK E. WEIDLER
SECRETARY

EDGAR T. THORNTON, III
DEPUTY SECRETARY

April 28, 1995

U. S. Department of Energy
Los Alamos Area Office
Attn: Jeff Carmichael
P. O. Box 1663, Mailstop K498
Los Alamos, NM 87545

RE: Confirmed Release at **Technical Area 21**

Dear Mr. Carmichael:

The New Mexico Environment Department has received notice of a release from an underground storage tank system at the above address. The New Mexico Underground Storage Tank Regulations outline steps that must be taken to investigate and clean up this release. The regulations tell you exactly what information to gather and report at each step. Within three days you must follow up the verbal release report with an additional verbal report summarizing abatement procedures taken and the results of the initial investigation. Within seven days, you must send a written report which includes this same information to the UST Bureau at the above address.

Please direct all future correspondence to me at the above address or call 827-0158 if you have questions or need a complete set of UST regulations.

If you find that you cannot meet a deadline prescribed by the regulations, you may apply for an extension, as long as you do so before the deadline passes. See Section 1221 for more details. The Department appreciates your voluntary cooperation.

Sincerely,

A handwritten signature in cursive script, appearing to read "Anthony Moreland".

Anthony Moreland
Geologist
Underground Storage Tank Bureau

enclosures: Regs Part XII

cc: NMED District II Office
NMED Espanola Field Office
Read File

SITE SUMMARY

Site Name: Technical Area 21 (DP Canyon)
Location: Los Alamos National Laboratory (LANL)
Project Mgr: Anthony Moreland
Consultant: LANL
Site Priority: #751 on Third Priority List

Brief History:

This site has been investigated by LANL. They have reported that their site is clean although they found petroleum contamination in the DP Canyon streambed below yet upgradient of their site. LANL conducted further investigations and remediated the site via source removal. The report submitted indicates the site is cleaned up. However, the contamination in the seeps in DP Canyon has been referred to Surface Water Quality Bureau (Harvey Decker @ 672-0459) and though we could close this site we should get concurrence from Harvey (written concurrence).