



GARY E. JOHNSON
GOVERNOR

State of New Mexico
ENVIRONMENT DEPARTMENT
Hazardous & Radioactive Materials Bureau
2044 Galisteo Street
P.O. Box 26110
Santa Fe, New Mexico 87502
(505) 827-1557
Fax (505) 827-1544



PETER MAGGIORE
SECRETARY

PAUL R. RITZMA
DEPUTY SECRETARY

Memorandum

To: John Kieling, LANL Facility Manager, RCRA Permits Management Program
Through: John Tymkowych, Program Manager, Inspection/Enforcement Program
From: Mark Coffman, Inspector, Inspection/Enforcement Program
Date: 01/19/00
Re: TA-21, Bldg. 61, Permitted Storage Bldg. Closure Verification

On Thursday, June 17, 1999, I conducted a closure verification inspection of this structure. The building has been cleaned and emptied of all hazardous wastes with the exception of two drums of rinsate, from the eighth episode of the floor decon, which are non-hazardous. The outside storage area pad is empty as well. Upon submittal of an approved final closure report to the RCRA Permits Management Program, this verification inspection will be considered complete and will be closed.

Cc: file



10564

J2

interoffice
M E M O R A N D U M

to: John Tymkowych
from: John Kieling JK
subject: LANL TA-21-61 Closure Verficiation
date: May 13, 1999

LANL has submitted a Closure Certification of the TA-21-61 storage unit and it has been reviewed and seems to be in order. This activity is a carryover from the EPA/NMED 1998 Grant. I would appreciate it if your program could visit the site and provide a short memo indicating the adequacy of the closure. Please contact me so I can provide details of the closure prior to a visit to site. Also, I can set up the visit with the appropriate LANL contact if needed.

Thank you for your assistance.

HRMB PHOTO SHEET

FACILITY: LANL

PHOTO #: 1

DATE: 6/17/99

LOCATION: TA-21, Bldg-61

DESCRIPTION: front of bldg-

VIOLATION: _____



PHOTO #: ~~1~~

DATE: ~~AAW 2~~

LOCATION: ~~6/17/99~~

DESCRIPTION: _____

VIOLATION: _____



TY: LANL

#: 2, 3, 4 (Panorama)
6/17/99

ION: Bldg. 61

PTION: Inside. LANL
employee by front
door - Linstate dr
from cleaning floor
on left. (9th or 8-
ION: floor rinse?).

#: _____

ION: _____

PTION: _____

PTION: _____

6 17 99



6/17/99

FACILITY: LANL
PHOTO #: 5, 6 (Panorama)
DATE: 6/17/99
LOCATION: Bldg. 61
Behind Bldg. - 61,
Outside Storage Pad.

DESCRIPTION: _____

VIOLATION: _____



6/17/99

PHOTO #: _____
DATE: _____
LOCATION: _____

DESCRIPTION: _____

VIOLATION: _____

New Mexico Environment Department
Hazardous & Radioactive Materials Bureau
P.O. Box 26110
Santa Fe, NM 87502

Negatives
LANL, TA-21, Bldg. 61
closure verification

6/17/99

M.V.C.