

gla

Los Alamos National Laboratory

UNIVERSITY OF CALIFORNIA

Duplicate



Environmental Restoration Project
MS M992
Los Alamos, New Mexico 87545
505-667-0808/FAX 505-665-4747

HSWA LAMU 4/11/89/35



Date: July 17, 1997
Refer to: EM/ER:97-273

Mr. Benito Garcia
NMED-HRMB
P.O. Box 26110
Santa Fe, NM 87502

SUBJECT: FIELD UNIT 4 SAMPLING ACTIVITIES AT TA-35

Dear Mr. Garcia:

Field Unit 4 is planning to perform supplemental Phase I sampling activities at TA-35 on or about July 30, 1997, through approximately August 29, 1997. Field activities will include collecting 197 surface and subsurface soil samples from 35 hand auger holes and 15 boreholes.

Samples will be collected as shown in the table below.

Location	Number of Samples	Sample Type	Analyses
PRS #(s) 35-003(h)	4	surface and subsurface soil	Gamma spectroscopy, SR-90, Tritium
PRS #(s) 35-003(j and k), 35-014(d), and 35-015(b)	8	surface and subsurface soil	VOC, SVOC, PCB, TPH
PRS #(s) 35-009(a)	42	surface and subsurface soil	Gamma spectroscopy, Isotopic Pu, Isotopic U, SR-90, Tritium
PRS #(s) 35-009(b)	24	surface and subsurface soil	Gamma spectroscopy, Isotopic U
PRS #(s) 35-009(c)	20	surface and subsurface soil	Gamma spectroscopy, Sr-90, Tritium
PRS #(s) 35-009(d)	16	surface and subsurface soil	Gamma spectroscopy




72

PRS #(s) 35-014(a)	24	surface and subsurface soil	Gamma spectroscopy, Sr-90
PRS #(s) 35-014(b)	9	surface and subsurface soil	SVOC, TPH, PCB
PRS #(s) 35-004(m) and 35-014(g ₂)	18	surface and subsurface soil	Gamma spectroscopy, Isotopic U
PRS #(s) 35-014(g ₁) and 35-016(n)	8	surface and subsurface soil	Gamma spectroscopy, Isotopic Pu, Isotopic U
PRS #(s) 35-016(b)	4	surface and subsurface soil	Gamma spectroscopy, Isotopic Pu, Isotopic U
PRS #(s) 35-016(j)	4	surface and subsurface soil	Gamma spectroscopy, Isotopic Pu, Isotopic U
PRS #(s) 35-016(q)	12	surface and subsurface soil	Gamma spectroscopy
PRS #(s) 35-016(p)	4	surface and subsurface soil	Gamma spectroscopy, Isotopic Pu, Isotopic U

If you have any questions or concerns please call me at (505) 667-0819.

Sincerely,



David McInroy
Environmental Restoration Project

DM/ss

Cy: M. Alexander, ESH-18, MS K497
R. Bohn, EM/ER, MS M992
S. Bolivar, EES-13, MS H865
D. Bradbury, EM/ER, MS M992
G. Coffin, EM/ER, MS M992
L. Dale, SAIC, MS J521
M. Gilgosch, LAAO, MS A316
J. Jansen, EM/ER, MS M992
D. Neleigh, EPA, R.6, 6PD-N
A. Pratt, EES-13, MS J521
T. Taylor, LAAO, MS A316
M. Leavitt, NMED-GWQB
G. Saums, NMED-SWQB
S. Yanicak, NMED-AIP, MS J993

EM/ER File, MS M992
RPF, MS M707