

TAS4



Dhawan, Neelam, NMENV

From: Dhawan, Neelam, NMENV
Sent: Tuesday, January 12, 2010 2:52 PM
To: 'Jarrett Rice'; 'Worth, Edwin'
Cc: Cobrain, Dave, NMENV
Subject: Completion Report for Pore-Gas Monitoring System Boreholes at MDA H

Jarrett

I'm reviewing the Completion Report for Pore-Gas Monitoring System Boreholes at Material Disposal Area H, dated December 2009. Section 7.2 describes well construction activities but it does not say if bentonite seals above and below each sampling interval were hydrated as required by the approved Work Plan (August 2009). I would appreciate clarification of this issue.

Thanks, Neelam

Neelam Dhawan

Environmental Specialist, Hazardous Waste Bureau New Mexico Environment Department 2905, Rodeo Park Drive East, Building 1 Santa Fe, NM 87505 Phone (505) 476-6042 / Fax (505) 476-6030 Main HWB Phone (505) 476-6000

