

KOHLHAAS

C O R P O R A T I O N

May 2, 1990

Signetics Company
9201 Pan American Fwy.
POB 10272
Albuquerque, NM 87184

Attn: Richard Timmons

Dear Richard:

Per your request for information regarding pressure testing of the 5000 gallon waste solvent tank, on your purchase order #159879KC.

In accordance with Kohlhaas Corporation testing procedure as well as UL142 guide lines, this tank was tested in the following manner:

1. Applying internal air pressure to the test pressure level of not less than 5 nor more than 7 psig.
2. Using soap suds at all welded connections to detect leaks for repair.
3. Defects are repaired and tank is then re-tested.

Should there be any need of further assistance in this matter, please do not hesitate in contacting us.

Sincerely,



Charles A. Kohlhaas, P.E.

