

26 SPK ABQ - Red



February 11, 1992  
RPW 92-123

Dr. Herbert Grover  
Permit Group Coordinator  
Hazardous and Radioactive Materials Bureau  
State of New Mexico  
Harold Runnels Building  
1190 St. Francis Drive  
Santa Fe, NM 87502

RE: Safety-Kleen Corporation  
Albuquerque, NM  
Operating Permit NMD000804294-1

Dear Mr. Grover:

As per Module IV, Tanks IV. H. 1. and Attachment II-7 Closure Plan, we are making the 45 day notification of partial closure of the existing underground tank (12,000 gallon waste tank). The procedures will be followed according to the Closure Plan Attachment II-7 of the permit. As the project is scheduled, we will notify you so you can be present during activities involving soil sampling. Anne Lunt of our Remediations Department will be coordinating this project. Her phone number is 310-831-3903.

If you have any further questions, please contact me at (714) 593-3985.

Sincerely,

*Robert P. Wachsmuth*  
Robert P. Wachsmuth  
Environmental Engineer  
Denver Region

RPW:rg

Attachments

cc A. Lunt  
J. Bard  
W. Olson  
7-008-01

*Enclosure  
not  
found*

